

l of ll North (front) elevation.



2 of 11

Looking southwesterly along So. Alpine Street, showing neighborhood context.



3 of ]]
East elevation, showing pergola and textured brick outside end chimney.



4 of 11 East elevation



5 of 11 South (rear) elevation.



6 of 11 West elevation, showing wrap-around veranda added at NW corner.



7 of 11 Entry stairhall, looking south



8 of 11 Living room, looking east.



Breakfast room, looking west.

Steven Murr photo, 1981 City of Cornelius PO Box 607 Cornelius, OR 97113

9 of 11



10 of 11
Dining room, looking south.



ll of ll Second floor stairway landing.