

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

RECEIVED MAR 2 3 1976

DATE ENTERED JUL 6 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Millwood (Lambert Brewer House)

AND/OR COMMON Same

2 LOCATION

CITY, TOWN

__VICINITY OF

COUNTY

STATE

Salvisa

Mercer

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Photographic Associates, 1253 South Third

DATE OF PHOTO

NEGATIVE FILED AT Street, Louisville, Kentucky

1969

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

View of the original front of the house taken from the southwest. The center portion is the original section of the house. The door on the foreground opens into the "dog-trot."



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED MAR 2 3 1976

DATE ENTERED JUL 6 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER F	
TYPE ALL ENTRIES FINCLOSE WITH PHOTOGRAPH	

1 NAME

HISTORIC

Millwood (Lambert Brewer House)

AND/OR COMMON

Same

2 LOCATION

CITY, TOWN

VICINITY OF

COUNTY

STATE

Salvisa

Mercer

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Photographic Associates, 1253 South Third Street, Louisville Kentucky.

DATE OF PHOTO

1969

NEGATIVE FILED AT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

Interior photo of the hall-parlor showing the enclosed corner staircase, and 2 of 8 the mantel. The door on the right leads to the east wing.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

MAR 2 3 1976

DATE ENTERED JUL 6 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1	NAME
	TANKATA

HISTORIC

Millwood (Lambert Brewer House)

AND/OR COMMON

Same

2 LOCATION

CITY, TOWN

___VICINITY OF

COUNTY

STATE

Salvisa

Mercer

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Photographic Associates, 1253 South Third Street, Louisville, Kentucky.

1969

NEGATIVE FILED AT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

РНОТО NO.

Interior photo of the south wall in the hall showing distinctive woodwork of the exterior door on the right.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

MAR 2 3 1976

DATE ENTERED JUL 6 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORM	1S
TYPE ALL ENTRIES FNCLOSE WITH PHOTOGRAPH	

1 NAME

HISTORIC

Millwood (Lambert Brewer House)

AND/OR COMMON

Same

2 LOCATION

CITY, TOWN ____VICINITY OF

COUNTY

STATE

Salvisa

Mercer

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Photographic Associates, 1253 South Third Street, Louisville, Kentucky.

DATE OF PHOTO

1969

NEGATIVE FILED AT

4 IDENTIFICATION

DESCRIBE VIEW. DIRECTION. ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

Interior photo of the dining room. Notice the window and door moldings.

рното по.

40/8



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

MAR 23 1976

DATE ENTERED

1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- LENCLOSE WITH PHOTOGRAPH

1 NAME

Millwood (Lambert Brewer House)

AND/OR COMMON

Same

2 LOCATION

city, town Salvisa VICINITY OF

COUNTY

STATE

Mercer

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Photographic Associates, 1253 South Third

Street, Louisville, Kentucky.

DATE OF PHOTO

1969

4 IDENTIFICATION

Interior photo showing the cupboards and fireplace in the master bedroom.

PHOTO NO.

5 of 8



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED MAR 2 3 1976

DATE ENTERED JUL 6 1978

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Millwood (Lambert Brewer House)

AND/OR COMMON

Same

2 LOCATION

CITY, TOWN
Salvisa

__VICINITY OF

COUNTY

STATE

Mercer

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Photographic Associates, 1253 South Third Street, Louisville, Kentucky.

DATE OF PHOTO

1969

NEGATIVE FILED AT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

Interior photo of the kitchen fireplace. The side of the smokehouse can be seen through the door.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS U	SE ONL	ΥΥ	
RECEIVED	MAR	3 1 1976	
DATE ENTE	RED	JUL 6	1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

. 1	NA	ME
	IAV	TAIL

HISTORIC

Millwood (Lambert Brewer House)

AND/OR COMMON

Same

2 LOCATION

CITY. TOWN Salvisa __VICINITY OF

COUNTY

STATE Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT

Mary Cronan

DATE OF PHOTO

January, 1976

NEGATIVE FILED AT

Kentucky Heritage Commission

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 7 0 8

Photo taken from the south showing the original facade of Millwood. The one-story wing on the left is the kitchen and the wing on the right, the master bedroom. Both were added ca. 1826.

INT: 2983-75



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

RECEIVED MAR 3 1 1976

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Millwood (Lambert Brewer House)

AND/OR COMMON Same

2 LOCATION

city, town Salvisa VICINITY OF

COUNTY

STATE Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Mary Cronan

DATE OF PHOTO January, 1976

NEGATIVE FILED AT

Kentucky Heritage Commission

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

РНОТО NO. 🐉

Taken from the south, photo of the original section of Millwood, ca. 1795. Notice the molding around the door and windows.