



THE WALES JOHNSON HOUSE
WOODSTOCK, WINDSOR COUNTY, VERMONT
LEIGH JOHNSON AUGUST, 1991

NEGATIVE ON FILE AT VERMONT
DIVISION FOR HISTORIC PRESERVATION
VIEW LOOKING NORTH-NORTH WEST
CONTEXT VIEW, U.S. RT. 4 IN FORE-
GROUND, OLD HIGHWAY BEYOND, HILLS
IN BACKGROUND.

PHOTO #1.



THE WALES JOHNSON HOUSE

WOODSTOCK, WINDSOR COUNTY, VT

LEIGHT JOHNSON AUGUST, 1991

NEGATIVE ON FILE AT VERMONT
DIVISION FOR HISTORIC PRESERVATION

VIEW LOOKING NORTH - NORTH WEST

3/4 VIEW OF FRONT OF BUILDING

SHOWING CARRIAGE BARN, ELL, WING, +
MAIN BLOCK

PHOTO # 2,



THE WALES JOHNSON HOUSE

WOODSTOCK, WINDSOR COUNTY, VERMONT

LEIGH JOHNSON August, 1991

NEGATIVE ON FILE AT VERMONT
DIVISION FOR HISTORIC PRESERVATION

VIEW LOOKING SOUTH; 3/4 VIEW
OF REAR OF BUILDING SHOWING
Main Block, Wing, Ell, + Carriage Barn

Photo #3



THE WALES JOHNSON HOUSE
WOOD STOCK, WINDSOR COUNTY, VERMONT
LEIGH JOHNSON AUGUST, 1991

NEGATIVE ON FILE AT VERMONT
DIVISION FOR HISTORIC PRESERVATION.

VIEW looking SOUTH WEST

Detail of East Gable with decorative
wall shingling, vergeboards, flared wall
with dentilled moulding, cornice of
house and porch with brackets.

Photo #4



THE WALES JOHNSON HOUSE

WOODSTOCK, WINDSOR COUNTY, VERMONT

LEIGH JOHNSON AUGUST, 1991

NEGATIVE ON FILE AT VERMONT
VT DIVISION FOR HISTORIC PRESERVATION

VIEW LOOKING EAST; INTERIOR VIEW
OF FRONTHALL AND ENTRY, MAIN BLOCK.

PHOTO #5.



THE WALES JOHNSON HOUSE

WOODSTOCK, WINDSOR COUNTY, VERMONT

LEIGH JOHNSON

AUGUST, 1991

NEGATIVE ON FILE AT

VERMONT DIVISION FOR

HISTORIC PRESERVATION

INTERIOR VIEW, CORNER

CUPBOARD AND DINING ROOM

WAINSCOTTING.

PHOTO #6