



St. Mark's Episcopal Church

Wash Co., Md

by: K.R. Sanford

Aug. 1998

Neg- Md SHPO

North facade with masonry
wall; central entry portal w/ gate

WA-II-024

1 OF 10



St. Mark's Episcopal Church
Washington Co, Md.

by: KR SANFORD

Aug 1998

Neg - Mo SHPO

North facade

WA-II-024

2 OF 10



St Mark's Episcopal Church
Washington Co., Md

by: KR. SANFORD


Aug. 1998

Neg- Md SAPO

North-West facade

WA-II-024

3 OF 10



St. Mark's Episcopal Church
Washington Co., Md.

by K.R. Sanford


Aug. 1998

Neg - Md SHPO

Southwest facade, showing new
sacristy addition

VIA - I - 024

4 OF 10



St. Mark's Episcopal Church

Washington Co., Md

by: KR Sanford

Oct. 1998

Neg - Md SHPO

East facade showing sacristy addition
tie-in to original structure

WA-II-024

5 of 10



St Mark's Episcopal Church
WASH. Co., Md.

Aug 1998, by - KR Santard

NFG - Md SHPO

South facade (rear) with cemetery

WA-II-024

6 OF 10



St Mark's Episcopal Church

Wash. Co. Md.

by: Rev. P. F. ...

Feb 1940

Neoptoma Md. 4700

interior, facing South

WA-II-034

1 OF 10



St. Mark's Episcopal Church

Wash. Co Md.

by: K.R. Sanford

2/98

Negative: Md. SHPO

Interior facing north: center aisle with gallery, front door, pews


WA-II-024

8 OF 10





Something went wrong while we were encoding this page.
Please check the log file to find out the details.



St. Mark's Episcopal Church,
Washington Co., Md

by - KR. Sanfai

Oct 1998

Neg - Md SHPO

View northward; door of
new sacristy in center
old exterior wall on
left.

WA-II-024

10 OF 10