



CE-229

Nathan and Susannah
Harris House
Rts. 273 + 276, Harrisville
Cecil County, Md.
R. Michael Borland, M.D.
Date June 20, 1983
Neg. at MHT, Annapolis, Md.

Camera is facing North-
East.

(20TH-CENTURY PORCH HAS
BEEN REMOVED SINCE PHOTO
WAS TAKEN)

1/18



CE-229

Nathan and Susannah
Harris House
Rts. 273 + 276, Harrisville,
Cecil County, Md.
R. Michael Borland, M.D.
Date June 20, 1983
Neg. at MHT, Annapolis, Md.

South Elevation of House
(camera facing North).

(20TH-CENTURY PORCH HAS BEEN
REMOVED SINCE PHOTO WAS
TAKEN.)

2/18



N.+ S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M.Borland
7/28/83
Neg at MHT

South elevation of
house. Dated rectangular
stone is shown.
CE#229

3/18



CE-229

Nathan and Susannah
Harris House
Rts. 273 + 276
Harrisville, Cecil
County, Md.

R. Michael Borland, M.D.

Date: June 20, 1983

Dated Stones on
South facade of the house.

NEG. AT M.H.I., ANNAPOLIS
4/18



CE-229

Nathan and Susannah

Harris House

Rts. 273 + 276, Harrisville,
Cecil County, Md.

R. Michael Borland, M.D.

Date June 20, 1983

Neg. at MHT, Annapolis, Md.

Staircase to second floor
with camera facing north.

DURING RESTORATION.


5/18



N. + S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M. Borland
7/28/83
Neg at MHT

Staircase leading to 2nd
floor. Camera looking
NNE.

CE #229


AFTER RESTORATION!
6/18



CE-229

Nathan and Susannah

Harris House

Rts. 273 + 276, Harrisville,
Cecil County, Md.

R. Michael Borland, M.D.

Date: June 20, 1983

NEG. AT M.H.T., ANNAPOLIS

Fireplace in 1st floor
front (south) room.
Camera facing northeast.

DURING RESTORATION

7/18





CE-229

Nathan and Susannah
Harris House
Rts. 273 + 276
Harrisville, Cecil
County, Maryland
R. Michael Borland, M.D.

NEG. AT M.H.T., ANNAPOLIS

Date: June 20, 1983

Large, walk-in fireplace
in main cooking area.
Camera is facing SW.

DURING RESTORATION

8/18





N. + S. Harris House
Rts 276 and 273
Harrisville, Md.

R. M. Borland
7/28/83
Neg at MHT

WINDER STAIR,
left of walk-in fireplace
in main cooking area.
Camera looks west.
CE #229

~~XXXXXXXXXX~~
AFTER RESTORATION

9/18



CE-229

Nathan and Susannah

Harris House

Rts. 273 + 276

Harrisville, Cecil County,
Maryland

R. Michael Borland, M.D.

NEG. AT M.H.T., ANNAPOLIS

Date: June 20, 1983

Beaded beam ceiling in
1st floor main cooking
area.

Camera is facing South.

DURING RESTORATION

 10/18



N.+S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M. Borland
7/28/83
Neg at MHT

Shaker peg board in main
cooking area, 1st floor.
Camera looking East.

~~AFTER RESTORATION~~

CE #229



11/18



N. + S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M. Borland
7/28/83
Neg at MHT

1st floor room, NE corner.
Camera looking East.
AFTER RESTORATION
CE# 229



12/18



N. + S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M. Borland
7/28/83
Neg at MHT

1st floor room, SE corner,
camera looking East.
Fireplace and window.

AFTER RESTORATION
CE # 229


13/18



N. + S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M. Borland
7/28/83
Neg at MHT

2nd floor room, SE corner
room. Camera looking East.
CE #229


AFTER RESTORATION

14/18



Something went wrong while we were encoding this page.
Please check the log file to find out the details.

N.+ S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M.Borland
7/28/83
Neg at MHT

2nd floor room. NE corner
room. Camera looks East.

AFTER RESTORATION

CE #229


15/18



N.+ S. Harris House
RTs 276 and 273
Harrisville, Md.

R.M.Borland
7/28/83
Neg at MHT

Suffolk latch with bean
cusp on attic door.

CE# 229
~~XXXXXXXXXX~~

AFTER RESTORATION

16/18



N.+ S. Harris House
Rts 276 and 273
Harrisville, Md.

R.M. Borland
7/28/83
neg at MHT

Attic
Looking East.
CE #229

~~CONFIDENTIAL~~

17/18



CE-229

Nathan and Susannah

Harris House

Rts. 273+ 276, Harrisville,
Cecil County, Md.

R. Michael Borland, M.D.

Date: June 20, 1983

NEG. AT M.H.T., ANNAPOLIS

Basement wall under
walk-in fireplace in
main cooking area.

Camera is facing West.

18/18