



1. F.D. Rose Building - Rose Court
2. Muncie, Indiana
3. Gooden Associates Architects,
Photographer
4. Date: August 10, 1983
5. Negatives at Gooden Associates
Architects
6. View looking southwest to show
context of existing conditions
7. Photograph #1



1. F.D. Rose Building - Rose Court
2. Muncie, Indiana
3. Gooden Associates Architects, Photographer
4. Date: August 10, 1983
5. Negatives at Gooden Associates Architects
6. View looking southwest to show the east
and north facades context and existing
conditions
7. Photograph #2



1. F.D. Rose Building - Rose Court
2. Muncie, Indiana
3. Gooden Associates Architects, Photographer
4. Date: August 10, 1983
5. Negatives at Gooden Associates Architects
6. View looking north showing entrance facade and context
7. Photograph #3



1. F.D. Rose Building - Rose Court
2. Muncie, Indiana
3. Gooden Associates Architects, Photographer
4. Date: August 10, 1983
5. Negatives at Gooden Associates Architects
6. View looking south showing the first
floor interior atrium space
7. Photograph #4



1. F.D. Rose Building - Rose Court
2. Muncie, Indiana
3. Gooden Associates Architects, Photographer
4. Date: August 10, 1983
5. Negatives at Gooden Associates Architects
6. View looking south showing the second floor interior atrium space
7. Photograph #5



1. F.D. Rose Building - Rose Court
2. Muncie, Indiana
3. Gooden Associates Architects, Photographer
4. Date: August 10, 1983
5. Negatives at Gooden Associates Architects
6. View looking southwest on first floor at interior facade and existing conditions.
7. Photograph #6

208



1. F.D. Rose Building - Rose Court
2. Muncie, Indiana
3. Gooden Associates Architects, Photographer
4. Date: August 10, 1983
5. Negatives at Gooden Associates Architects
6. View looking east on second floor at interior facade and existing conditions
7. Photograph #7