



- 1) Name of Property: Early Winters Ranger Station
(Work Center)--Residence #1004
- 2) City and State: Vicinity of Winthrop, Washington
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking north easterly, at main south-facing facade.
- 7) Photograph Number: 08-05-1004



- 1) Name of Property: Early Winters Ranger Station
(Work Center)--Warehouse #2201
- 2) City and State: Vicinity of Winthrop, Washington
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, at the south
(main) facade
- 7) Photograph Number: 08-05-2201



- 1) Name of Property: Early Winters Ranger
(Work Center)--Garage #2311
- 2) City and State: Vicinity of Winthrop,
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service
a1 Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly, a
gable end, main west-facing facade
- 7) Photograph Number: 08-05-2311



- 1) Name of Property: Early Winters Ranger Station
(Work Center)--Barn #2402
- 2) City and State: Vicinity of Winthrop, Washington
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southeast, at north gable end, west-facing main facade
- 7) Photograph Number: 08-05-2402



- 1) Name of Property: Early Winters Ranger Station
(Work Center)--Gas House #2501
- 2) City and State: Vicinity of Winthrop, Washington
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, at west elevation and main south-facing facade
- 7) Photograph Number: 08-05-2501



- 1) Name of Property: Early Winters Ranger Station
(Work Center)--Power House #2613
- 2) City and State: Vicinity of Winthrop, Washington
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking north at south gable and, main entry
- 7) Photograph Number: 08-05-2613



- 1) Name of Property: Early Winters Ranger Station
(Work Center)--Office #2002
- 2) City and State: Vicinity of Winthrop, Washington
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, at west gable end, main south-facing facade
- 7) Photograph Number: 08-05-#2002



- 1) Name of Property: Early Winters Ranger Station, Office #2002
- 2) City and State: Vicinity of Winthrop, WA
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly, at rear north-facing elevation of office
- 7) Photograph Number: 08-05-2002-2



- 1) Name of Property: Early Winters Ranger Station
(Work Center)--Residence #1003
- 2) City and State: Vicinity of Winthrop, Washington
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking north of main south-facing facade.
- 7) Photograph Number: 08-05-1003



- 1) Name of Property: Early Winters Ranger Station,
Ranger's Residence #1003
- 2) City and State: Vicinity of Winthrop, WA
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking northwesterly, at south and
east elevations of Ranger's residence, connecting
breezeway, and attached garage.
- 7) Photograph Number: 08-05-1003-2



- 1) Name of Property: Early Winters Ranger Station,
Ranger's Residence #1003
- 2) City and State: Vicinity of Winthrop, WA
- 3) Photographer: Curtis A. Edwards
- 4) Date: 9/84
- 5) Negative Location: USDA Forest Service, Region-
al Office, Recreation Unit, CRM files.
- 6) Description: Looking southwesterly, at rear
elevation; showing details of breezeway, bay with
scrolled lintel, handcarved pendants
- 7) Photograph Number: 08-05-1003-3