

Albuquerque, N.M. West Facade Facing Edith Blvd. with Sala Double Doors Robert Willson, Albuquerque Historic Landmarks Survey, 1978



Albuquerque, N.M. North Facade with Kitchen Entrance Robert Willson, Albuquerque Historic Landmarks Survey, 1978

2.



Albuquerque, N.M. Fireplace in Sala Robert Willson, Albuquerque Historic Landmarks Survey, 1978

3



Albuquerque, N.M. Southwest Corner Facade Detail Mary Davis, Albuquerque Historic Landmarks Survey, 1981



Albuquerque, N.M. Corner Fireplace, Packed Adobe Floor-South Center Room Robert Willson, Albuquerque Historic Landmarks Survey, 1978



Albuquerque, N.M.

Corner Fireplace-South Center Room Robert Willson, Albuquerque Historic Landmarks Survey, 1978



Albuquerque, N.M. View into North Bedroom Robert Willson, Albuquerque Historic Landmarks Survey, 1978



Juan Antonio Garcia House Albuquerque, N.M. Worn Threshold Sill Mary Davis, Albuquerque Historic Landmarks Survey, 1981

8



Albuquerque, N.M. Beaded Vigas in Sala Mary Davis, Albuquerque Historic Landmarks Survey, 1981