
### United States Department of the Interior Heritage Conservation and Recreation Service

### National Register of Historic Places Inventory—Nomination Form



See instructions in *How to Complete National Register Forms* Type all entries—complete applicable sections

## 1. Name

<b>historic</b> Be	eechland				
and/or commo	n same as abov	e			
2. Loc	ation 5,	6 Natche	z of	-f U561	
street & numbe	One mile north erfive miles eas				NA_ not for publication
city, town	latchez nic	_X_ v	vicinity of	congressional district	t
state Missi	issippi	code 28	county	Adams	code ]
<b>3. Cla</b>	ssificatio	n			
Category district building(s) structure site object	Ownership public private both Public Acquisiti <u>NA</u> in process being conside	on Accessil yes:	cupied in progress ble	Present Use agriculture commercial educational entertainment government industrial military	museum park _X_ private residence religious scientific transportation other:
	ner of Pro	perty			
name Gene	Radzewicz		<b>-</b>		
street & numbe					
	atchez		vicinity of	state	Mississippi 39120
<u></u>	gistry of deeds, etc.	Office of the Adams County	Chancery	Clerk	
street & numbe	r Courthouse S	quare			
city, town	Natchez			state	Mississippi 39120
<u>6. Rep</u>	oresentati	on in Exi	sting	Surveys	
title NA			has this pro	operty been determined	elegible? yes _X no
date				federal st	tate county local
depository for	survey records				
city, town				state	•

### 7. Description

Condition		Check one
excellent	deteriorated	X unaltered
_X_ good	ruins	altered
fair	unexposed	

Check one \_X\_ original site

moved date \_\_\_\_

NA

#### Describe the present and original (if known) physical appearance

Entered from a mile-long plantation drive on the northern side of the Hutchins Landing Road about five miles east of its intersection with U.S. Highway 61 South, Beechland is a one-and-a-half story frame, Greek Revival residence set upon brick foundation piers. The steeply pitched gabled roof is pierced by two interior brick chimneys. The southerly facade and the rear northerly elevation are fronted by an undercut gallery which originally featured a full molded entablature supported by molded box columns linked by a railing of rectangularsectioned balusters with molded handrail; however, sections of the entablature are missing and the original columns and railing were removed by a former owner and stored in an outbuilding. The present owner plans to repair and restore the original columns and railing. The pilasters with molded capitals that frame both the front and rear walls of the house are original and echo the design of the original columns. Both the five-bay facade and the five-bay northern rear wall are finished in stucco on lath which has been scored and penciled in imitation of stone and with a molded base having two fascias. The windows of the front and rear elevations feature molded architrave surrounds, all windows are filled with sixover-six, double-hung sash, and some are closed by original shutter blinds. The frontispiece entrance, which is located in the center bay of the facade, consists of a full molded entablature supported by pilasters. A single-leaf door with six molded panels is framed by a transom and sidelights over molded panels. Access to the interior from the rear gallery is provided through doorways located in the center three bays of the rear wall. These doorways feature molded architrave surrounds and are filled with single-leaf doors with four, molded panels.

The interior plan is a double-pile plan with wide central passage. All four downstairs rooms and the hallway are identically trimmed with molded architrave door and window surrounds, four-paneled and molded doors, wooden and pilastered mantel pieces, and molded bases with two fascias. Decorative plaster work consists of a foliated centerpiece in the central hallway, a concentric circle centerpiece in the easterly front room, and an unusual magnolia leaf centerpiece in the westerly front room. The two rear chambers each feature a large fireplace wall closet with full-size, four-paneled and molded door. The open stairway is entered at the rear of the hallway in a series of winders to continue in a straight southerly flight to terminate in a second-story hallway. The stairway, which has simply turned balusters, features a probably unique architectural detail in which the turned newel and the turned handrail are linked by a wooden doughnut.

Two bedrooms are located on each side of the second-story hallway. The second story is trimmed in an identical manner to the first story except that the bases have a single fascia and are beaded. Each of the four bedrooms features an original closet with full-size, four-paneled and molded door.

The integrity of Beechland is excellent. The front and rear exterior walls retain their original paint and white penciling, the faux-bois treatment of all doors remains intact, the interior walls have never been painted, the mantel pieces retain their original fake black marbleing, the bases exhibit the original black paint, and most of the original hardware has survived. No original outbuildings or significant landscape features remain except for a family cemetery.

### 8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799 X 1800–1899 1900–	Areas of Significance—C archeology-prehistoric archeology-historic agriculture X architecture art commerce communications		Iandscape architectur Iaw Iiterature Iiterature Iiterature IIII IIIII IIIIII IIIIIIIII IIIIIIIII	e religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	unknown	Builder/Architect	known	

#### Statement of Significance (in one paragraph)

a concern of h

€. •**,**.(. (

Beechland' is a significant example of vernacular Greek Revival plantation architecture. The house exhibits the typical Mississppi, mid-nineteenth century, plantation form of a oneand-a-half story, five-bay, frame house with undercut gallery, molded box columns, and brick foundation piers. Frequently, the front wall of such houses was finished in horizontal matched boards, and occasionally, like Beechland, in stucco on lath that is scored and penciled in imitation of stone. Beechland derives added significance from this facade treatment, which is also repeated on the rear elevation, because it retains its original peachcolored tint and white penciling. In addition, the interior decorative scheme of the house is also intact and includes white plaster walls, grained doors, black baseboards, and mantel pieces with fake black marbleing. A probably unique and well executed architectural feature of the house is the stairway which features a wooden doughnut at the union between the turned newel post and the turned handrail. Unusual features of the house are the matching galleries of the front and rear elevations, the division of the upper half story into four bedrooms, the original closets of the two, downstairs rear rooms and the four second-story bedrooms, and the magnolia leaf centerpiece of the westerly front parlor. Beechland was recently purchased by Gene Radzewicz who plans to restore the house as a residence. Although the original columns and railings of the front and rear galleries were removed by a former owner, the present owner has located them in a storage building and plans to repair and restore them to the house. The outstanding interior integrity of the house will be preserved.

est drive successful part to

for and setting

# 9. Major Bibliographical References

K

Miller, Mary Warren. Historic Natchez Foundation, Natchez, Mississippi. Inspection of Beechland, June 5, 1982.

10. Geographic	al Data		
Acreage of nominated property Quadrangle nameKingston, N UMT References			Quadrangle scale <u>1:62500</u>
A 1 5 6 5 9 7 5 0 3 4 Zone Easting North	7 14 3 18 15 hing	B Zone	Easting Northing
C		D F H	
right angle corners and ec of the roof ridge of the b house.	qual sides of ( nouse. The sid	500 feet each des of the fig	property forms a four-sided figure wit with the center being the center point gure are parallel to the walls of the
List all states and counties for			
state <sub>NA</sub>	code	county	code
state	code	county	code
organization Historic Natchez street & number P. O. Box 12			date June 6, 1982 elephone (601) 442-2500
			Micciccippi 20120
	ric Prese		Officer Certification
The evaluated significance of this p	roperty within the s	tate is:	
national	state	local	
	y for inclusion in the	e National Register	oric Preservation Act of 1966 (Public Law 89– r and certify that it has been evaluated vation and Recreation Service.
State Historic Preservation Officer s	ignature	Gb+ 1. 1.	Saly
title Deputy State Historic	Preservation (	Officer	date September 27, 1982
For HCRS use only I hereby certify that this prope Allow Byen Weeper of the National Register Attest:	nty is included in th		a the <u>uly</u> /cz date
Chief of Registration			