

STATE Form No. 10-301a UNITED STATES DEPARTMENT OF THE INTERIOR (7/72) NATIONAL PARK SERVICE Washington COUNTY NATIONAL REGISTER OF HISTORIC PLACES Thurston PROPERTY PHOTOGRAPH FORM FOR NPS USE ONLY BI DATE ENTRY NUMBER (Type all entries - attach to or enclose with photograph) S DEC Z NAME 0 Tenino Depot COMMON: AND/OR HISTORICE LOCATION STREET AND NUMBER: U RECEIVED West side of Town CITY OR TOWN: DEC 4 2 1974 Tenino -STATE: COUNTY NATIONAL CODE CODE 5 Washington 53 REGISTER Thurston PHOTO REFERENCE Z Jacob E. Thomas PHOTO CREDIT: 1974 DATE OF PHOTO: ш NEGATIVE FILED AT: Washington State Parks and Recreation Commission ш 4 IDENTIFICATION DESCRIBE VIEW, DIRECTION, ETC. West and south facades, view to the northeast.

U.S. COVERNMENT DOINTING OFFICE.



Form No. 10-301a (Pev. 10-7-)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY
RECEIVED MAR 1 0 1976
DATE ENTERED

SEE INSTRUCTIONS IN HOW TO	COMPLETE NATIONAL REGISTER FORMS
TVDE ALL ENTRIE	S ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Tenino Depot

AND/OR COMMON

2 LOCATION

CITY, TOWN

Tenino

\_\_VICINITY OF

Thurston

STATE Washington

3 PHOTO REFERENCE

PHOTO CREDIT David M. Hansen

DATE OF PHOTO December 1975

NEGATIVE FILED AT Washington State Parks & Recreation Commission

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View of northwest face of relocated structure; tracks of former main line can be seen on grade between roadway and depot.

PHOTO NO.

1 of 2



(Pev. 10-7 +)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY
RECEIVED MAR 1 0 1976

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Tenino Depot

AND/OR COMMON

2 LOCATION

CITY, TOWN

Tenino

\_\_VICINITY OF

COUNTY Thurston

STATE Washington

3 PHOTO REFERENCE

PHOTO CREDIT David M. Hansen

DATE OF PHOTO Dec

December 1975

NEGATIVE FILED AT Washington State Parks & Recreation Commission

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

2 of 2

View of northeast face of building showing backfilled excavation; tracks are out of photo to the right.

excertion ...