Form No. 10-301a
(7/72)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

STATE	
Washington	
COUNTY	
Thurston	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE
	DEC 27 1974

SEE INSTRUCTIONS

1. NAME

COMMON: Tenino Depot

AND/OR HISTORIC:

2. LOCATION

STREET AND NUMBER:
West side of Town

CITY OR TOWN:
Tenino

STATE:	CODE	COUNTY:	CODE
Washington	53	Thurston	067

RECEIVED
DEC 4 1974
NATIONAL REGISTER

3. PHOTO REFERENCE

PHOTO CREDIT: Jacob E. Thomas

DATE OF PHOTO: 1974

NEGATIVE FILED AT:
Washington State Parks and Recreation Commission

4. IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC.

West and south facades, view to the northeast.

#1 of 1

Form No. 10-301a
(Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY
RECEIVED MAR 10 1976
DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Tenino Depot

AND/OR COMMON

2 LOCATION

CITY, TOWN Tenino ____VICINITY OF COUNTY Thurston STATE Washington

3 PHOTO REFERENCE

PHOTO CREDIT David M. Hansen DATE OF PHOTO December 1975

NEGATIVE FILED AT Washington State Parks & Recreation Commission

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View of northwest face of relocated structure; tracks of former main line can be seen on grade between roadway and depot.

PHOTO NO.
1 of 2

Form No. 10-301a
(Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY
RECEIVED MAR 10 1976
DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Tenino Depot

AND/OR COMMON

2 LOCATION

CITY, TOWN Tenino ___VICINITY OF COUNTY Thurston STATE Washington

3 PHOTO REFERENCE

PHOTO CREDIT David M. Hansen DATE OF PHOTO December 1975

NEGATIVE FILED AT Washington State Parks & Recreation Commission

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View of northeast face of building showing backfilled excavation; tracks are out of photo to the right.

PHOTO NO. 2 of 2

Showing backfilled
of Excavation