









Harland Sanders Cafe, Corbin, KY

Photo circa 1987 showing the cafe prior to restoration. Note the "new" vestibule and vinyl siding. The Manager's Office door is covered over and the gable ends are covered with stucco.



Harland Sanders Cafe, Corbin, KY Photo in December, 1989, during exterior restoration. Vinyl siding and covering on gable ends removed and original window and door openings revealed. Note that the original finish materials survive on the north gable end.