

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. Me-181

| | | | |
|---|--|---|--|
| 1. Historic Name(s) <u>Stone quarters on Burgin Rd.</u> | | 22. ADD/County <u>Bluegrass Mercer</u> | |
| Original Owner | | 23. U.S.G.S. Quadrant (15'/75') <u>Harrodsburg vic.</u> G.I.S. Mod. | |
| 2. Present Name | | 24. UTM Reference | |
| 3. Location <u>Highway 152, 9/10 mi. E of 68</u> | | Zone <u>16</u> Easting <u>691960</u> Northing <u>4181340</u> | |
| 4. Owner's Name <u>Mrs. Lewis F. Isom</u> | | 25. Coordinate Accuracy | |
| 5. Owner's Address <u>High 68, Harrodsburg, Ky. 40330</u> | | 26. Prehistoric Site <input type="checkbox"/> Object | |
| 6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | | Historic Site <input type="checkbox"/> Structure | |
| 7. Visible from road Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | | Building <input checked="" type="checkbox"/> Other | |
| 8. Ownership Private <input checked="" type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> | | 27. National Register District Name: | |
| 9. Local Contact/Organization | | 28. Significance Evaluation | |
| 10. Site Plan with North Arrow <u>See attached boundary form</u> | | 29. Status <input type="checkbox"/> Date | |
| 11. Architect | | National Landmark <input type="checkbox"/> | |
| 12. Builder | | National Register <input type="checkbox"/> | |
| 13. Date <u>2nd '419 ch. A. [3] B. []</u> | | Landmark Certificate <input type="checkbox"/> | |
| 14. Style A. <u>G.R. period [C]</u> B. <input type="checkbox"/> | | Kentucky Survey <input type="checkbox"/> | |
| 15. Original Use <u>quarters []</u> | | Local Landmark <input type="checkbox"/> | |
| 16. Present use <u>shop</u> | | HABS/HAER <input type="checkbox"/> | |
| 17. Condition <u>fair [C]</u> | | 30. Historic Theme Primary <u>architecture [C]</u> Secondary <u>black history [CB]</u> Other <input type="checkbox"/> | |
| 18. Description <u>4 bay 1 story double cell dry stone quarters. Rough masonry, few tool marks, large white limestone, re-worked and repointed with concrete. Wooden lintels, mitered corner frames. Interior chimney on E. end. (over)</u> | | 31. Endangered Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> | |
| (Continue on Back) | | 32. Preservation Project Status <input type="checkbox"/> | |
| 19. History | | Actual Cost in \$1,000s <input type="checkbox"/> | |
| 20. Significance <u>Typical stone quarters</u> | | 33. ATTACH PHOTO <u>in attached envelope</u> | |
| 21. Source of Information <u>inspection</u> | | Roll No. _____ | |
| | | Picture No. _____ | |
| | | Direction _____ | |
| | | 34. Prepared by: <u>C.M. Woolley</u> | |
| | | 35. Organization _____ | |
| | | 36. Date <u>1983</u> | |
| | | 37. Revision Dates _____ 38. Staff Review _____ | |

18. Cont.:

Roof has been heightened. W. end
has frame gable above eave line.

Located on downhill grade
behind yard of main house, probably
built on site of an earlier house.

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at A, at the N.E. corner of a shed behind the brick house, thence W. parallel to front of quarters, W. 140 ft to B, thence at right angles N. 100 ft to C, E 140 ft to D, and S. 100 ft to the beginning, containing the stone quarters and stone foundation, about 1/3 acre.

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

