OHIO HISTORIC INVENTORY

JUN 2 7 1979 Ohio Historic Preservation Office Ohio Historical Control Ohio Historical Center Columbus, Ohio 43211

			Columbus, Onio 43211	
1. No. 8	4. Pres	4. Present Name(s)		
2. County Loc				9 9 ș
3. Location of Negatives	5. Othe	or Name(s)		
OHS				
6. Specific Location	rhland Dd	16. Thematic Category	28. No. of Stories	រ ខ
North side of Highland Rd.		F, H, I	29. Basement? Yes 🗆	5
j ust east of the Cuyahoga River		17. Date(s) or Period 1825-1827	No 🗆 30. Foundation Materiai	ummit
7. City or Town if Rural, Township & Vicinity agamore Hills		18. Style or Design	31. Wali Construction	
8. Site Rian with North Arrow		19. Architect or Engineer	load-bearing masonr	ŀ
WAVEHN RD. WAVEHN RD. HIGHLAND RD. HIGHLAND RD.			32. Roof Type & Materiai	
		20. Contractor or Builder	33. No. of Bays	
		21. Original Use, if apparent	Front Side	Loc
		canal lock 22. Present Use	34. Wall Treatment cut stone/concrete	7 8
			35. Plan Shape rectangle	N 0
9. Coordinates		23. Ownership Public ऄ Private □	36. Changes Addition □ (Explain Altered ¥	ېس
Lat. Long.		24. Owner's Name & Address,	in #42) Moved 🗆	F'
U.T.M. Reference		St äte owof 0., Dept. of Public Works	37. Condition xloterios fair	"Re
17452720	4570800	65 S. Front St., Columbus	x x textor	ed
Zone Easting 10. Site 🗆	Northing Structure	25. Open to Yes 24 Public? unrestricted No 🗆	38. Preservation Yes D Underway? No St	Чo
	Object	26. Local Contact Person or Organization	39. Endangered? Yes 🗆	ock
11. On National Yes 🗆 Register? No 🗷	12. is it Yes ⊠ Eligible? No □	Summit County Hist. Soc. 27. Other Surveys in Which Included	By What? No 🕃	:- -
13. Part of Estab. Yes 🗆	14. District Yes 🖾	historic civil engineering	40. Visible from Yes 🗆	
Hist. Dist.? No 28 15. Name of Established Di	Potent'i? No	landmark, Ohio Council ASCE	Public Road? No Da 41. Distance from and	1
		Approx. Acreage: less than 1	Frontage on Road	
42. Further Description of I	mportant Features			Ι-,
Lock is standard mitered gate type. The lock chamber is				ç
		The cut stone construction 1905. Both gates are missin		ā
There is water i	in the lock ch	amber, though the canal is		
dry at this point. The lock is almost obscured by thickets. Stonework and concrete are deteriorated.				9
43. History and Significance hat portion of t		e Canal between Akron and Cle	veland was opened	
uly 4, 1827. Th	e drop of 395	feet between the two cities	was accomplished	
y 41 locks in 35 on Lock No. 34	miles. At 1	east one local history gives ot suggest the origin of that	the name "Red Lock"	
ritten that all	woodwork of t	he locks and sluices was pain	ted Indian red.	
44. Description of Environm		vicinity of the Jaite Paper	Mill The look	
and surrounding	land has become	me a dumping ground.	MIII. INC IOCK	
45. Sources of information				[
	Historical As	sociation, A Reminiscent	46. Prepared by Carol Poh Miller	
History of Brecksville (Berea, 0.: Berea Publishing 47. Organization Company, 1961), p. 22.				Í
		, selec. and ed. William A.	48. Date 49. Revision Date(s)	ĺ
		tate University Press, 1969).		