



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Jackie Sluss

Date of photo: 1980

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View from southwest

SEP 13 1982

Photo 1 of 10



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Jackie Sluss

Date of photo: 1980

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View from northeast

SEP 13 1982

Photo 2 of 10



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

View from northwest
Photo 3 of 10

SEP 13 1982



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

SEP 13 1982

Detail of gable end on front (south) facade.

Photo 4 of 10



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

SEP 13 1982

Detail of front entrance on south facade.

Photo 5 of 10



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

West end of basement, view from northwest.

SEP 13 1982

Photo 6 of 10



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

Southeast corner classroom on first floor,
view from northwest.

SEP 13 1982

Photo 7 of 10



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

Stair well on west end, view from half-story landing
between first and second floors, view from south.

Photo 8 of 10

SFP 13 1082



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

Second floor hallway, view from east.

SEP 13 1982

Photo 9 of 10



St. Mary's Academy
East Eleventh Street
Devils Lake, ND 58301

Photo credit: Steve Schell

Date of photo: 1980

Location of negative: Downtown Redevelopment
Post Office Box 773
Devils Lake, ND 58301

Northeast corner room on third floor, view from
southeast.

SEP 13 1982

Photo 10 of 10