



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

HARRIET BEECHER STOWE HOUSE

AND/OR COMMON

Stowe House

**2 LOCATION**

CITY, TOWN

Brunswick

\_\_\_ VICINITY OF

COUNTY Cumberland

STATE Maine

**3 PHOTO REFERENCE**

PHOTO CREDIT

Polly M. Rettig, Landmark Review Project

DATE OF PHOTO

July, 1975

NEGATIVE FILED AT

Historic Sites Survey, Washington, D.C.

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO 1

West (front) and south elevations of main block; portions of rear ell  
and converted barn (restaurant).



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC HARRIET BEECHER STOWE HOUSE

AND/OR COMMON  
Stowe House

**2 LOCATION**

CITY, TOWN Brunswick

\_\_\_ VICINITY OF

COUNTY  
Cumberland

STATE  
Maine

**3 PHOTO REFERENCE**

PHOTO CREDIT Polly M. Rettig, Landmark Review Project DATE OF PHOTO July 1975

NEGATIVE FILED AT Historic Sites Survey, Washington, D.C.

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View from west showing converted barn (restaurant) and adjacent motel structure.

PHOTO NO. 2