



Name: CHERBOURG ROUND BARN; K-862

Location: Vicinity of Little Creek, DE

Photographer: Dean E. Nelson

Date: July 1978

Location of Negative: Hall of Records, Dover, DE

Description: Looking to the south

Photograph Number: #1

OCT 2 1978

DEC 22 1978



Name: CHERBOURG ROUND BARN: K-862

Location: Vicinity of Little Creek, DE

Photographer: Dean E. Nelson

Date: July, 1978

Location of Negative: Hall of Records, Dover, DE

Description: Looking to the east; the silos to the right retain their original wooden shingles; note portions of the original sheet iron gutter at the eaves.

Photograph Number: #2

OCT 2 1978

DEC 22 1978



Name: CHERBOURG ROUND BARN: K-862

Location: Vicinity of Little Creek, DE

Photographer: Dean E. Nelson

Date: July 1978

Location of Negative: Hall of Records, Dover, DE

Description: A view of the interior ground floor, taken from
the main entrance.

Photograph Number: #3

OCT 2 1978

DEC 22 1978



Name: CHERBOURG ROUND BARN: K-862

Location: Vicinity of Little Creek, DE

Photographer: Dean E. Nelson

Date: July, 1978

Location of Negative: Hall of Records, Dover, DE

Description: First floor, showing concrete platform which encircles the sunken earthen floor; the iron pipes formed feeding positions above a trough which is now filled with concrete.

Photograph Number: #4

OCT 2 1978

DEC 22 1978



Name: CHERBOURG ROUND BARN: K-862

Location: Vicinity of Little Creek, DE

Photographer: Dean E. Nelson

Date: July, 1978


Location of Negative: Hall of Records, Dover, DE

Description: Detail of junction of girder with cast concrete wall. Weight is supported principally by cast iron columns.

Photograph Number: #5

OCT 2 1978

DEC 22 1978



Name: CHERBOURG ROUND BARN: K-862

Location: Vicinity of Little Creek, DE

Photographer: Dean E. Nelson

Date: July, 1978

Location of Negative: Hall of Records, Dover, DE

Description: Loft on 2nd story; illustrating manner in
which the rafter system rests upon cast concrete walls.

Photograph Number: #6

OCT 2 1978

DEC 22 1978



Name: CHERBOURG ROUND BARN: K-862

Location: Vicinity of Little Creek, DE

Photographer: Dean E. Nelson

Date: July, 1978

Location of Negative: Hall of Records, Dover, DE

Description: The rafter system as viewed from the loft floor; the plate for the second roof pitch appears as the lowest arc.

Photograph Number: #7

OCT 2 1978

DEC 22 1978