



NAME: Quartz Lake Patrol Cabin  
LOCATION: Glacier National Park, <sup>MT</sup> MT  
PHOTOGRAPHER: Historical Research Associates  
DATE OF PHOTOGRAPH: August 1982  
LOCATION OF NEGATIVE: Rocky Mountain  
Regional Office, National Park  
Service, Denver, CO  
PHOTO NUMBER: 1

A black and white photograph of the interior of a rustic log cabin. The walls are made of horizontal log sections. A large lantern hangs from the ceiling in the center. To the right, a teapot is hanging on the wall. Below the teapot is a rectangular tray. In the foreground, a window with a wooden frame is visible. Two signs are mounted on the wall to the left of the window.

QUARTZ LAKE  
ELEVATION 4395

QUARTZ LAKE 0710  
NO STOK ALLOWED IN  
CAMPFIRE  
WILD FIRES ONLY IN  
FIRE PLACES

Quartz Lake Patrol Cabin  
HS589

Interior

Quartz Lake Patrol Cabin  
Flathead Co., MT, Glacier NP  
Figure 1



**STOP**

Do not touch or move any of the equipment or materials in this room. This is a restricted area. Only authorized personnel are allowed to enter. If you are not authorized, please leave the room immediately. If you have any questions, please contact the supervisor.

Quartz Lake Patrol

· Cabin

HS 589

Interior

Quartz Lake Patrol Cabin

Flathead Co., MT, Glacier NP

Figure 2



USPS



FIRST AID KIT

Quartz Lake Patrol Cabin

Its 589

Interior

Quartz Lake Patrol Cabin  
Flathead Co., MT, Glacier NP

Figure 3