



Jennison House and Horse Barn

Rockledge Farm

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking northwest

Photograph 1



Jennison House, Pump House, Garage, and caretaker's cottage

Rockledge

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking southwest

Photograph 2



Jennison House

Rockledge Farm

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking southwest

Photograph 3



Jennison House

Rockledge Farm

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking northeast

Photograph 4



Horse Barn

Rockledge Farm

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking northwest

Photograph 5



Gazebo

Rockledge Farm

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at Vermont Division for Historic Preservation

View looking northeast

Photograph 6



Jennison House, Parlor

Rockledge

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking northeast

Photograph 7



Jennison House, Dining Room

Rockledge

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking west

Photograph B



Jennison House, sun room

Rockledge

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking north

Photograph 9



Jennison House, Stairway

Rockledge

Swanton, Vermont (Franklin County)

Photograph by Lauren Murphy

March 1988

Negative filed at the Vermont Division for Historic Preservation

View looking west

Photograph 10



Jennison House, Historic View, Summer 1922

Rockledge

Swanton, Vermont (Franklin County)

Photographer Unknown. Copied by Lauren Murphy from
The History of Swanton Vermont

Negative filed at the Vermont Division for Historic Preservation

View looking southeast

Photograph 11



Jennison House, Historic View, Summer 1908

Rockledge

Swanton, Vermont (Franklin County)

Photographer Unknown. Copied by Lauren Murphy from

The History of Swanton Vermont

Negative filed at the Vermont Division for Historic Preservation


View looking west

Photograph 12

Located about 10 Rods from Main Residence




LEONARD GROVE



ST. ALBANS HIGH GATE ROAD



COUNTRY ESTATE
OF
CLARK S. JENNISON
SWANTON VERMONT
APRIL 1920.



SCALE 50 FT TO THE INCH

PEABODY SLOSSON & SMYTH
INSURANCE BROKERS
NEW YORK
ENGINEERING DEPARTMENT

C. SMYTH ENGINEER

Plan of "Country Estate of Clark S. Jennison"

Rockledge Farm

Swanton, Vermont (Franklin County)

Copied by Lauren Murphy

Negative filed at the Vermont Division for Historic Preservation

April 1920 Insurance Map

Photograph 13