

Location: near Port Penn, Delaware

Photographer: George Rineer

Date: 1976

Location of Negative: OAHP, Heritage Cons. & Rec. Service, Dept. of Interior, Washington, D.C.

Description: View of light from east

Photograph Number: 1



Location: near Port Penn, Delaware

Photographer: George Rineer

Date: 1976

Location of Negative: OA&HP, Heritage Cons. & Rec. Service, Dept. of Interior, Washington, D.C.

Description: View of light from north. Rear of Keeper's House (on right) and Assistant Keeper's House (on left).

Photograph Number: 2

JUN 7 1978

NOV 1 5 1978



Location: near Port Penn, Delaware

Photographer: George Rineer

Date: 1976

Location of Negative: OA&HP, Heritage Cons. & Recreation Service, Dept. of Interior, Washington, D.C.

Description: View of Structural System of Range Light from base of tower

Photograph Number: 3



Location: near Port Penn, Delaware

Photographer: George Rineer

Date: 1976


Location of Negative: OA&HP, Heritage Conservation & Rec. Service, Dept. of Interior, Washington, D.C.

Description: Masonry foundation for tower

Photograph Number:

JUN 7 1978

NOV 1 5 1978



Location: near Port Penn, Delaware

Name: Liston Range Rear Light Station

Photographer: George Rineer

Date: 1976

Location of Negative: OA&HP, Heritage Conservation & Rec. Service, Dept. of Interior, Washington, D.C.

Description: East side of Vestibule at base of staircase shell

JUN 7 1978

Photograph Number:



Location: Near Port Penn, Delaware

Photographer: George Rineer

Date: 1976

Location of Negative: OA & HP, Heritage Conservation & Rec. Service, Dept. of Interior, Washington, D.C.

Description: Door of Vestibule at base of light

Photograph Number: 6



Location: near Port Penn, Delaware

Photographer: George Rineer

Date: 1976

Location of Negative: OA&HP, Heritage Cons., & Recreation Service, Dept. of Interior, Washington, D.C.

Description: View of Staircase looking up

Photograph Number: 7



Location: near Port Penn, Delaware

Photographer: George Rineer

Date: 1976

Location of Negative: OA&HP, Heritage Conservation & Rec. Service, Dept. of Interior, Washington, D.C.

Description: View of Lighting Apparatus

Photograph Numbers



Location: Near Port Penn, Delaware

Photographer: Bureau of Archaeology & Hist. Pres. Staff

Date: 1978


Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Keeper's House from South

JUN 7 1978

Photograph Number: 9

NUV 1370



Location: Near Port Penn, Delaware

Photographer: Bureau of Archaeology & Hist. Pres. Staff

Date: 1978

Location of Negative: Div. of Historical & Cultural Affairs

B/AGHP, Hall of Records, Dover, Delaware 19901

Description: Assistant Keeper's House from South

NOV 1 5 1978

Photograph Number: 10



Location: Near Port Penn, Delaware

Photographer: Bureau of Archaeology & Hist. Pres. Staff

Date: 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Liston Range Rear Light Station Complex from

South

NOV 1 5 1978

Photograph Number: 11