



**Property name:** Powell - Redmond House  
**Location:** 23 Columbia St., Clifton, Mason Co. WV

**Photo credit:** Michael Pauley

**Date of photo:** 12/82

**Negative filed at:** Dept. of Culture & History  
Historic Preservation Unit, The Cultural  
Center, Capitol Complex, Charleston, WV 25301

**Description of photo:**

Front (W) and Side (N) elevation

**Direction of photo:** Looking S.E.





**Property name:** Powell - Redmond House  
**Location:** 23 Columbia St., Clifton, Mason Co. WV

**Photo credit:** Michael Pauley  
**Date of photo:** 12/82  
**Negative filed at:** Dept. of Culture & Historic Preservation Unit, the Cultural Center, Capitol Complex, Charleston, WV 25301  
**Description of photo:**

Side (N) eleva. and Rear (E) eleva.

**Direction of photo:** Looking S.W.





**Property name:** Powell - Redmond House  
**Location:** 23 Columbia St., Clifton, Mason Co, WV

**Photo credit:** Michael Pauley  
**Date of photo:** 12/82  
**Negative filed at:** Dept. of Culture & History  
Historic Preservation Unit, The Cultural  
Center, Capitol Complex, Charleston, WV 25301  
**Description of photo:**

Side (S) elev. distant elev.

**Direction of photo:** Looking N.





Property name: Powell - Redmond House  
Location: 23 Columbia St., Clifton, Mason Co., WV

Photo credit: Michael Pauley

Date of photo: 12/82

Negative filed at: Dept. of Culture & History,  
Historic Preservation Unit, The Cultural Center  
Capitol Complex, Charleston, WV 25305

Description of photo:

Ornamental Plasterwork Detail, cornice;  
Ballroom 1st floor

Direction of photo:





**Property name:** Powell - Redmond House  
**Location:** 23 Columbia St., Clifton, Mason Co., WV

**Photo credit:** Michael Pauley  
**Date of photo:** 12/82

**Negative filed at:** Dept. of Culture & History  
Historic Preservation Unit, The Cultural Center  
Capitol Complex, Charleston, WV 25305

**Description of photo:**

Ornamental Plaster Detail, 1st floor  
ballroom, ceiling rosette

**Direction of photo:**