



MAR 26

LOOKING FOR





MAR 95

Looking South



MAR 96

Looking North FROM MAIN STREET



11/21/94



DAVIS AND ELKINS HISTORIC DISTRICT
Elkins, West Virginia
Historic photo of second floor landing of main staircase



96

MARBLE WAINSCOT (IN BATHS OF C MAIN GUEST ROOMS)



94

LGR: NEW WP20, OLD FINISH, NEW FINISH



Billings Room

96



96

An WASTING BEDROOM (3RD FLOOR)





96

COLUMN DETAIL IN BALCONY AREA



96

NEW TILES, SENATOR'S SUITE





96

DETAIL PARLOR MANTLE



9C

DINING ROOM / CARPENTER SHOP



9C

DINING ROOM

MANTEL



96

NEW TILES IN LIBRARY FIREPLACE

TILES FROM THE NETHERLANDS



96

LIBRARY FIREPLACE INSERT



74
REPLACEMENT BALUSTRE



MAR 96

MAIN STAIRWAY LANDING



96

PARLOR MANTEL



KITCHEN



DINING ROOM



Dinner Room



DOMESTIC MAIL



WALTER HALL



LARGE BROWN



SMALL ROOMS



VASTAVES BATH



UASAGIAS BATH



KITCHEN



**DAVIS AND ELKINS HISTORIC
DISTRICT**

**Elkins, West Virginia
Gatehouse**

Photo: Victor Thacker, 1994




**DAVIS AND ELKINS HISTORIC
DISTRICT**
Elkins, West Virginia
Gatehouse
Photo: Victor Thacker, 1994



**DAVIS AND ELKINS HISTORIC
DISTRICT**

**Elkins, West Virginia
Gatehouse**

Photo: Victor Thacker, 1994




**DAVIS AND ELKINS HISTORIC
DISTRICT**

Elkins, West Virginia

Icehouse

Photo: Victor Thacker, 1994



DAVIS AND ELKINS HISTORIC DISTRICT
Elkins, West Virginia
Icehouse
Photo: Victor Thacker, 1994



DAVIS AND ELKINS HISTORIC DISTRICT
Elkins, West Virginia
Icehouse
Photo: Victor Thacker, 1994



old

bathroom

2nd floor

Halleimust

1987




stained glass
windows

men stucco

Halliburst

1987



Stained glass
window - 1st
landing -
main staircase
Hallehurst

1987



1st landing -
main

staircase

from

ground hall

Halliburst

1987



left front
" cloak room"

Hallie Hurst

entrance -

original

cabinetry

but new light

1987



front door

Hallieburst -

knock head knocker

missing