Iowa	Site	Inventory
------	------	-----------

Office of Historic Preservation Iowa State Historical Department East 12th & Grand Avenue Des Moines, Iowa 50319

Site Number <u>48</u>
District Name
Map Reference #_48

## Identification

30

1. Site Name	Round Barr	, Dubuque T	wp., Dubuque	County			
2. Village/Town/City_			nship_Dubuque_	•	_County_DL	ibuau	e
3. Street Address		scade Road		· · · · · · · · · · · · · · · · · · ·		•.	
4. Legal Location		T89N		R3E		34	SEZ
0	Urban: Rural:	subdivision township		block range	parcel section		subparcel % section of % section
5. UTM Location: zon	ee	asting 688,45	0_northing_4,70	<u>4,680;</u> Acreag	e <u>less</u>	<u>than</u>	one acre
6. Owner(s) Name	Wayne_Ohmert	, Don Ohmer	<u>t</u>				
7. Owner(s) Address	Street addre	Drive	Dubuque	·	owa	5200	
,			(City)		State)		(Zip)
8. Use: PresentE		barn	Original	Dairy ba	<u>rn</u>		<u> </u>
Description	1915						
9. Date of Construction 0. Building Type:	on	Architect	Builder UNK				<u></u>
single-family dwo		ndustrial educational	☐ oth ☐ pub	er institutional lic		🔲 relig 🛢 agric	
□ commercial 1. Exterior Walls: □ c ■ otherC		brick bo	ard and batten 🛛 sh	ingles 🗌 stucc	o		·
2. Structural System:	□ wood frame with aring walls □ iro	n frame 🗌 stee	ts 🏢 wood frame wit I frame with curtain w	h light members valls 🗌 reinford	s (balloon fra ced concrete	me)	
other the building enda the building enda the building enda the building of the building of the building of the building of the building enda the bu	angered? Eno [ 	n land 🗌 woodla		tbuildings 🗌 de			commercial
18. Map			19. Photo	54 Frame 28	8 View	<u></u>	
BUQUE			MISSISSIPPI RIVER LAND ACQUISITK Z JO DAVIESS CO TO TO TO TO TO TO TO TO TO T	VBD: A ba:	circle a	80' i enter	n diameter point of barn only.
	78 m // I	1 C C C C C C C C C C C C C C C C C C C					

## Significance

(Indicate sources of information for all statements)

#### 20. Architectural significance

a. Key structure/individually may qualify for the National Register

b. Contributing structure

C. Not eligible/intrusion

#### N/A

Continuation of 14. Integrity.

Interior - Circular aound central silo. Diameter -60'. Silo - clay tile 14' diameter. Stone foundation. Roof - conical, roll roofing over wood shingles, large projecting gabled granery.

	True-Round;	lowa/King type; Johnston Brothers.
21. Historical Significance	Theme(s) True-Rouns;	Specialty Contractor; Clay Tile Supplier.

" a. Key structure/individually may qualify for the National Register

b. Contributing structure

C. Not eligible/intrusion

See Continuation Sheet.

22. Sources (for primary and secondary sources, give complete facts of publication: author, title, place of publication, date, etc.):

Prepared by	_Date
Address	Telephone
Organization	

# For Office of Historic Preservation Use Only

1. Office Information Sources on this Property	Review and Compliance Project:
County Resource File	
🗌 Windshield Survey	Other
🗌 National Register	Other
Grants-In-Aid:	Other
Determination of Eligibility	
	3. Photo Images
2. Subject Traces	-
a	
b	
(	·
d	
е	

Iowa Site Inventory Office of Historic Preservation

Iowa State Historical Department East 12th & Grand Avenue Des Moines, Iowa 50319 Site Number \_\_\_\_\_48

**Continuation Sheet** 

### Item Number(s)

One of eighteen round barns known to have been built on an lowa farm with vitrified hollow clay tiles believed to have been supplied by the Johnston Brothers' Clay Works of Webster County and with a design similar to the Johnston Brothers' promotional, prototype barn located next to the clay pits. The names of the actual builders of this barn, and their connection to the Johnston Brothers, is unknown.

This barn is specifically characterized as a Johnston Brothers' sub-type by its exterior wall of "...small red clay tile in the lower story and larger tile above..." (Soike 1983). The conical roof is another common feature of the Johnston Brothers' design. The clay tile exterior wall and silo wall generally classify this barn as an lowa Agricultural Experiment Station / Matt King influenced type. The use of structural clay tile was one of the later improvements in the history of round barns.