

88-17-32

Bennington Railroad Station
Bennington, Vermont
Credit: Hugh H. Henry
Date: June 1987
Negative filed at Vermont Division
for Historic Preservation
South elevation; view looking
northwest.
Photograph 1



8877.32

Bennington Railroad Station
Bennington, Vermont
Credit: Hugh H. Henry
Date: June 1987
Negative filed at Vermont Division
for Historic Preservation
West and south elevations; view
looking northeast.
Photograph 2




88732

Bennington Railroad Station
Bennington, Vermont
Credit: Hugh H. Henry
Date: June 1987
Negative filed at Vermont Division
for Historic Preservation
East and north elevations; view
looking southwest.
Photograph 3



88A-32

Bennington Railroad Station
Bennington, Vermont
Credit: Hugh H. Henry
Date: June 1987
Negative filed at Vermont Division
for Historic Preservation
Porte-cochere on east facade; view
looking northwest.
Photograph 4



86-17-67

Bennington Railroad Station
Bennington, Vermont
Credit: Weichert-Isselhardt Collection
Date: c. 1897
Negative filed at Vermont Division for
Historic Preservation
Preliminary sketch of west and south
elevations by W. C. Bull, architect.
Photograph 5



86-7-67

Bennington Railroad Station
Bennington, Vermont
Credit: Weichert-Isselhardt Collection
Date: c. 1910
Negative filed at Vermont Division for
Historic Preservation
South and east elevations; view looking northwest.
Photograph 6