



7703/12:34 1182-30 R0804 200

NOV 17 1978

Photo #1 JUL 24 1978  
Bow Valley Mills  
Cedar County, Nebraska  
South facade, Photo by D. Murphy.  
1977, NSHS #7703/12:34



7703/12:27

1182-20

F804 sec

NOV 17 1978

Photo #2

JUL 24 1978

Bow Valley Mills

Cedar County, Nebraska

north and west facades, Photo by  
D. Murphy, 1977, NSHS 7703/12:27



7703/12:32 1632-30 RB04 sel

NOV 17 1978

Photo #3 JUL 24 1978  
Bow Valley Mills  
Cedar County, Nebraska  
south and east facades, Photo by  
D. Murphy, 1977, NSHS #7703/12:32



Photo #4

NOV 17 1978

Bow Valley Mills

Cedar County, Nebraska

Structural detail, 2nd floor

looking south, Photo by D. Murphy,

1977, NSHS #7703/13:2

JUL 24 1978

7703/13:2 1182-16 R80 4 526



7703/12:29

1CB1-22

RBD4

SOL

JUL 24 1978

NOV 17 1978



7703/12:25

1CB3-206

8804

See

JUL 24 1978

NOV 17 1978