



1.

Christ Church
Chaptico, St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1993

Negatives at church office

West side with Tower, Door and Driveway

1/16



2.

Christ Church
Chaptico, St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1993

Negatives at church office

Apse with fenced key vault,
from East

2/16



3.

Christ Church
Chaptico, St. Marys County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1993

Negatives at church office

Apse with Box-type gravemarker
in foreground, from east

3/16



4.

Christ Church
Chaptico

St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1993

Negatives at church office

View of church and surrounding graveyard
from southeast

4/10



5,

Christ Church
Chaptico

St. Mary's County
Maryland

Photographer: Ronald I. Holyfield

Photographed June 1992

Negatives at church office

North Side

5/16



6,
Christ Church
Choptico
St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1992

Negatives at church office

Window, North side, where
door once was

6/
16



7.

Christ Church
Chaptico

St. Marys County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1992

Negatives at church office

Window, south side, where
door once was

7/16



8,

Christ Church
Chaptico

St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1992

Negatives at church office

Latch, front door

8/16



9.

Christ Church
Chapico

St. Marys County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1992

Negatives at church office

Columns from rear of church
toward baptismal font

9/16



Christ Church ¹⁰
Chaptico

St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1992

Negatives at church office

Top of column

10/16



11.

Christ Church
Chap^lice

St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1992

Negatives at church office

Apse with altar, stained glass
window, vaulted ceiling

11/16



12.

Christ Church
Chaptico

St. Mary's County
Maryland

Photographer: Ronald I. Holyfield

Photographed June 1992

Negatives at church office

Altar

12/16



13.

Christ Church
Chaptico

St. Mary's County
Maryland

Photographer: Ronald I. Holyfield
Photographed June 1992

Negatives at church office

Baptismal Font

83/16



14.

Christ Church

Chaptico

St Marys County

Maryland

Photographer: Ronald I. Holyfield

Photographed June 1992

Negatives at church office

View toward church door,
showing choir loft

14 / 16



©. Md. ART. Co.

15.

Christ Church
Chaptico
St. Mary's County
Maryland

Photographer UNKNOWN
Photographed shortly after
addition of Tower in 1916

Negatives in church office

View shortly after addition of
Tower, from west



15
10



16

Christ Church
Chaptico
St. Mary's County
Maryland

Photographer UNKNOWN
When photographed UNKNOWN

Negatives in church office

View Before Tower,
From West

16/16