



MINDEN
FLOUR
MILLING
COMPANY
INCORPORATED
MARCH 5
1906

MINDEN MILLING CO.

MINDEN MILLING CO.

MINDEN FLOUR MILLING CO. - #1

South-side view of mill located adjacent to
U.S. Highway 395 (foreground) in Minden, Nv.

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #2

North-side view of mill showing corrugated sheet metal sheds attached to the main brick structure, and the four 45'high by 23'diameter steel grain-storage silos. The V&T Railroad served the mill from this side.

OCT 17 1978

NOV 14 1978



FIRE
EXTINGUISHER

E0306

1/2 U.A.
100 FT.
34212
GRAY

1/2 U.A.
100
3421
GRAY

1/2 U.A.
100 FT.
342
GRA

1/2 U.A.
100 FT.
34212
GRAY


ANACONDA
FLEXIBLE LIQUID
CAL

MINDEN FLOUR MILLING CO. - #3

South-side (U.S.Hwy 395) one-story dock area (now enclosed) with corrugated sheet metal roof. South-side brick wall contains large windows looking into first-floor main room of brick structure. (Boxes are temporarily stored for Bently Nevada Corp).

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #4

Late 1800's Allis-Chalmers belt-driven
milling machine located on first floor.

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #5

View toward ceiling of first floor showing extra support posts and beams installed to support molasses tanks on second floor when mill was converted to a feed mill in 1942. Shown is east brick wall of main structure and one of many pine grain chutes (running diagonally top right to bottom middle).

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #6

Wooden work bench next to second-floor window overlooking U.S. Hwy 395.

OCT 17 1978

NOV 14 1978




MINDEN FLOUR MILLING CO. - #7

Second-floor view of pine grain bin (one of four against west brick wall) which extends up through third floor. Note use of full-measure 2" by 6" pine stacked flat to form bin walls and the smooth wood surface inside the bin created by constant flow of grain.

OCT 17 1978

NOV 14 1978




MINDEN FLOUR MILLING CO. - #8

Third-floor pine bin in middle of floor with intricate carpentry. Floor in background partially removed in 1942 to accomodate metal molasses tanks installed on second floor. Windows facing east.

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #9

View looking up to roof and loft area from third floor showing massive beams, machinery, and top of one of a number of storage bins within the mill. White object (lower left) is a smoke alarm installed in recent years.

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #10

Screw conveyor and chutes in loft area over third floor (looking in direction of silos to the west).

NOV 14 1978

OCT 17 1978



MINDEN FLOUR MILLING CO. - #11

View from loft area toward southeast corner of brick building looking down into molasses tanks.

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #12

View from approximately second-floor level looking into 3-story partition between silos and main brick building. A screened materials bin is at left.

OCT 17 1978

NOV 14 1978



MINDEN FLOUR MILLING CO. - #13

Huge bull-wheel with wooden teeth and wedges located in corrugated sheet metal roof over silos. West brick wall and one of many rope-driven wheels are in background.

NOV 14 1978

OCT 17 1978



MINDEN FLOUR MILLING CO. - #14

View looking west down catwalk over silos.
Note chutes which took grain from overhead
screw conveyor to silos below.

OCT 17 1978

NOV 14 1978



BRIDGE MILL, HUNTER, N.H.

VIEW OF BRIDGE MILL, LOOKING TO NORTHWEST
N.H. DIVISION OF FOREST, FISHERIES & AGRICULTURE
August, 1919

100
100



MINOEN MILL, MINOEN, NV.

DETAIL VIEW OF UPPER LEVEL WINDOW, ROOF ON
SOUTH EAST CORNER OF STRUCTURE WHERE
LOADING DOCK/STEEP JOIN 3 1/2 STOREY PORTION

AUGUST, 1978

NEVADA DIVISION OF HISTORIC PRESERVATION & ARCHAEOLOGY PHOTO

NOV 14 1978

OCT 17 1978