



STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

South elevation, view north



STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

North (rear) elevation,
view south



STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

Wagon shed at rear, view
northeast



STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

Barn in rear, view northeast



STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

Well east of house, view east



STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

Entrance hall and stairway,
view north




STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87

Negative filed with Conn.
Hist. Comm., Hartford

Paneling in first-floor east
middle room, view northeast

7




STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

Detail showing double posts
between east and west middle
rooms

8



STRONG HOUSE
Coventry, Connecticut

HRC Photo, 4/87
Negative filed with Conn.
Hist. Comm., Hartford

Shouldered posts and brace,
second-floor east end room,
view south

9