



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N. Atlantic, Portland, OR 97217
6. From south, Silcox Hut in its alpine environment, summit of Mt. Hood in background.
7. Photo #1



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N.
Atlantic, Portland, OR
97217
6. Looking northwesterly at the main facade
(south) of Silcox Hut.
7. Photo #2



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Looking southwesterly at north (rear) elevation of Silcox Hut. Photo also details exterior chimney on east gable end.
7. Photo #3



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Looking westerly, photo shows south-projecting wing, unpaved terracing. Missing wood shingle roof materials result from severe weather conditions and vandalism.
7. Photo #4




1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N.
Atlantic, Portland, OR
97217
6. Steel sash define windows of an awning type.
7. Photo #5



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Bronze plaque commemorating Ferdinand A. Silcox, Chief of the Forest Service, 1933-1939, whose efforts made possible the development of the Timberline Lodge Recreation Area. Plaque is mounted above fireplace on east wall.
7. Photo #6



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N.
Atlantic, Portland, OR
97217
6. Interior detail, routed ring post made from
large log.
7. Photo #7



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N.
Atlantic, Portland, OR
97217
6. Interior detail, hand hewn timber door hung
with decorative wrought-iron strap hinges.
7. Photo #8



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N.
Atlantic, Portland, OR
97217
6. Interior detail, stone stairs leading from
bull-wheel room up to dining room.
7. Photo #9



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: USDA Forest Service
4. Date: 1939
5. Negative Location: Negative #70746--Oregon
Historical Society
Collections, Portland, OR
6. From south, Silcox Hut under construction, 1939
7. Photo #10



Warming Cabin at the Top of the Ski Lift

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: USDA Forest Service
4. Date: 1939
5. Negative Location: Negative #70745--Oregon
Historical Society
Collections, Portland, OR
6. Looking northeasterly, Silcox Warming Cabin at
the top of the Magic Mile Ski Lift, summit of
Mt. Hood in background.
7. Photo #11



1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: USDA Forest Service
4. Date: 1939
5. Negative Location: Negative #70744--Oregon
Historical Society
Collections, Portland, OR
6. Looking easterly, Silcox Hut in use winter of 1939.
7. Photo #12