1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N. Atlantic, Portland, OR 97217
6. From south, Silcox Hut in its alpine environment, summit of Mt. Hood in background.
7. Photo #1

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Looking northwesterly at the main facade (south) of Silcox Hut.
7. Photo #2

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE,Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Looking southwesterly at north (rear) elevation of Silcox Hut. Photo also details exterior chimney on east gable end.
7. Photo #3

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE,Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Looking westerly, photo shows south-projecting wing, unpaved terracing. Missing wood shingle roof materials result from severe weather conditions and vandalism.
7. Photo #4

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE,Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Steel sash define windows of an awning type.
7. Photo #5

FERDINAND A. SILCOX
LODGE
RECREATION AREA

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE, Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Bronze plaque commemorating Ferdinand A. Silcox, Chief of the Forest Service, 1933-1939, whose efforts made possible the development of the Timberline Lodge Recreation Area. Plaque is mounted above fireplace on east wall.
7. Photo #6

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE,Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Interior detail, routed ring post made from large log.
7. Photo #7

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE,Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Interior detail, hand hewn timber door hung with decorative wrought-iron strap hinges.
7. Photo #8

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: Upward Trails
4. Date: 1983
5. Negative Location: Files of ICE,Ltd., 5520 N. Atlantic, Portland, OR 97217
6. Interior detail, stone stairs leading from bull-wheel room up to dining room.
7. Photo #9

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: USDA Forest Service
4. Date: 1939
5. Negative Location: Negative #70746--Oregon Historical Society Collections, Portland, OR
6. From south, Silcox Hut under construction, 1939
7. Photo #10

[illegible] Warming Cabin at the Top of the [illegible]

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: USDA Forest Service
4. Date: 1939
5. Negative Location: Negative #70745--Oregon Historical Society Collections, Portland, OR
6. Looking northeasterly, Silcox Warming Cabin at the top of the Magic Mile Ski Lift, summit of Mt. Hood in background.
7. Photo #11

1. Silcox Hut
2. Vicinity of Government Camp, OR
3. Photographer: USDA Forest Service
4. Date: 1939
5. Negative Location: Negative #70744--Oregon Historical Society Collections, Portland, OR
6. Looking easterly, Silcox Hut in use winter of 1939.
7. Photo #12