

Susan Ryan, photo, 2/1980
Filed with Connecticut Historical
Commission, Hartford, CT

Exterior, facade in context, north side of Elm Street, southeast view




JOHN COOK HOUSE, New Haven, CT Susan Ryan, photo, 2/1980

Filed with Connecticut Historical Commission, Hartford, CT


Exterior: facade and east side,

exterior: lacade and east side, south view
2 of 9



Susan Ryan, photo, 2/1980 Filed with Connecticut Historical Commission, Hartford, CT

Exterior, detail: front entrance, south south west view



JOHN COOK HOUSE, New Haven, CT
Susan Ryan, photo, 2/1980
Filed with Connecticut Historical

Commission, Hartford, CT

Exterior, detail: west entrance (closed up), southwest view

(closed up), southwest view



Susan Ryan, photo, 2/1980
Filed with Connecticut Historical
Commission, Hartford, CT

Exterior: rear and west side, north northwest view



JOHN COOK HOUSE, New Haven, CT Susan Ryan, photo, 2/1980 Filed with Connecticut Historical Commission. Hartford. CT

Interior: 1st floor, central hall. southwest view



Susan Ryan, photo, 2/1980
Filed with Connecticut Historical
Commission, Hartford, CT

Interior, detail: 1st floor, marble fireplace, southeast room, southeast view

f 9



JOHN COOK HOUSE, New Haven, CT
Susan Ryan, photo, 2/1980
Filed with Connecticut Historical

Commission, Hartford, CT
Interior: 3rd floor, ballroom,
northwest view

northwest view 8 of 9



Susan Ryan, photo, 2/1980
Filed with Connecticut Historical
Commission, Hartford, CT

Interior, detail: 3rd floor, east
 fireplace in ballroom,
 northwest view