DANIEL
D.Albright Farm
Marquam Vic.Ore.
E.Hoff, 1978,neg.
Looking west to
Granary,hse,barn
No. 1.79

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

DOE
OCT 30 1979

Eric C. Hoff Photo, 1978
2056-1/2 Lincoln
Eugene, OR 97405

11 SEP 1979

1 of 9 Looking northwesterly
Left to right: granary (1870), farmhouse (1865, remodeled 1904), and barn (1901).

DANIEL

D.Albright Farm
Marquam vic.,Ore.
P.Dole, 1978, neg.

Looking west to
front of 1901 barn
No. 2.

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

Philip H. Dole Photo, 1978
University of Oregon
Department of Architecture
Eugene, OR 97403

DOE
OCT 30 1979

2 of 9 Barn (1901)
South and east elevations

11 SEP 1979

DANICH

D.Albright Farm
Marquam vic. Ore.
P. Dole,1978,neg.

Looking east to
back of 1901 barn

No.3

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

DOE

OCT 30 1979

Philip H. Dole Photo, 1978
University of Oregon
Department of Architecture
Eugene, OR 97403

3 of 9 Barn (1901)
North and west elevations

11 SEP 1979

DANIEL,
D.Albright Farm
Marquam vic. Ore.
E.Hoff,1978, neg.
Ceiling, hewn fr.
Lower floor of
1901 barn
No.4

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

DOC
OCT 30 1979

Eric C. Hoff Photo, 1978
2056-1/2 Lincoln
Eugene, OR 97405

4 of 9 Interior of barn showing
hewn framing system, ground story

11 SEP 1979

DANIEL
D.Albright Farm
Marqaum vic.Ore.
P.Dole,1978, neg.
Looking east
Upper floor of
1901 barn
No.5

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

DDE
OCT 30 1979

Philip H. Dole Photo, 1978
University of Oregon
Department of Architecture
Eugene, OR 97403

5 of 9 Interior of barn showing framing and siding, upper story

11 SEP 1979

DANIEL

D.Albright Farm
Marquam vic. Ore.
P.Dole, 1978, neg.
Looking east to
Granary
No. 6 of 9

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

DOE
OCT 30 1979

Philip H. Dole Photo, 1978
University of Oregon
Department of Architecture
Eugene, OR 97403

6 of 9 Granary (1870)
West elevation

11 SEP 1979

DANIEL

D.Albright Farm
Marquam vic. Ore,
D.Jenkins,1978,neg

Looking north to
Smoke house

No.7

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

DOE
OCT 30 1979

David Jenkins Photo, 1978
2056-1/2 Lincoln
Eugene, OR 97405

11 SEP 1979

7 of 9 Smokehouse
West and south elevations

DANIEL

D. Albright Farm
Marquam vic. Ore.
D. Jenkins, 1978, neg
Looking east
to front elevatic
of house b. 1865
No. 8 19

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

ODE
OCT 30 1979

David Jenkins Photo, 1978
2056-1/2 Lincoln
Eugene, OR 97405

11 SEP 1979

8 of 9 Farmhouse (1865, remodeled 1904)
North and west elevations

DANIEL

D.AlbrightFarm
Marquam vic. Ore.
D.Jenkins,1978,neg
Looking west to
rear elev. house
woodshed, "cellar
No.9

Albright (Daniel) Farm Group
Marquam vicinity
Clackamas County, Oregon

DOE

OCT 30 1979

David Jenkins Photo, 1978
2056-1/2 Lincoln
Eugene, OR 97405

11 SEP 1979

9 of 9 Farmhouse (1865, remodeled 1904)
East (rear) elevation