

Location: E. Pine Street, Georgetown, Delaware Name: St. Paul's Episcopal Church

Photographer: Richard Carter

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Front view of church

Photograph Number: 1 of 13

DOE



SEP 2 5 1979

Location: E. Pine Street, Georgetown, Delaware

Photographer:Richard Carter

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs,


B/A&HP, Hall of Records, Dover, Delaware 19901

Description: View of Church from E. Pine Street showing

1940's addition at rear view of southwest wall.

Photograph Number: 2 of 13

20E NOV 1 3 1979



Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter

SEP 2 5 1979

Date: September, 1978


Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: View of southwest wall.

Photograph Number: 3 of 13

*po€* NOV | 3 1979



Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter

Date:September, 1978

Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware

Description: Church from the southwest showing rear wing and a portion of the cemetery.

Photograph Number: 4 of 13

00E NOV 1 3 1979



Location: E. Pine Street, Georgetown, Delaware


Photographer: Richard Carter

Date: September, 1978

Location of Negative:Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901
Description: Detail of steeple

Photograph Number: 5 of 13

1 3 1979



Name: St. Paul's Episcopal Church Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Southwest corner of church.

Photograph Number: 6 of 13



SEP 2 5 1979 St. Paul's Episcopal Church

E. Pine Street, Georgetown, Delaware Location:

Photographer: Richard Carter Date: September, 1978 Location of No : tive: Div. of Historical & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware 19901 Description: Interior of church showing ornamental beam work.

Photograph Number: 7 of 13



Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter


Date: September, 1978

Location of No of ye: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Rear of Church

Photograph Number: 8 of 13



Name: St. Paul's Episcopal Church SEP 2 5 1979

Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter

Date: September, 1978
Location of Negative: Div. of Historical & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware 19901 Description: The pulpit

Photograph Number: 9 of 13

00e

1979



**SEP** 2 5 1979

Name: St. Paul's Episcopal Church

Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter

Date: September, 1978


Location of Ecative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: A carved reading table

Photograph Number: 10 of 13

100 1 3 1979



SEP 2 5 1979 Name: St. Paul's Episcopal Church


Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs,

HB/A&HP, Hall of Records, Dover, Delaware 19901 Description: Detail of steeple

Photograph Number: 11 of 13



Location: E. Pine Street, Georgetown, Delaware

Photographer: Richard Carter

Date: September, 1978

Location of Negative: Div. of Historical & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware 19901 Description: Interior of Church, looking toward the altar

Photograph Number: 12 of 13



Name: St. Paul's Episcopal Church SEP 2 5 1979

Location: E. Pine Street, Georgetown, Delaware 19901

Photographer: Richard Carter

Date: September, 1978
Location of Negative: Div. of Historical & Cultural Affairs
B/A&HP, Hall of Records, Dover, Delaware 19901
Description: example of Victorian stained glass window.

Photograph Number: 13 of 13

3 1979