



Gwynne/Love Residence
El Paso County, Colorado
Photographer: Unknown
Locale of Negative: 730 N. Cascade Ave.
Colorado Springs, CO.

Date of Photo: Circa 1890
Photo 1 of 12
View looking southwest
Exterior-East & Northeast Facades



ONE WAY

570-6466
DANGER

Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,
Colorado Springs, CO

Date of Photo: August, 1986

Photo 2 of 12

View looking southwest

Exterior- East & Northeast Facades



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,
Colorado Springs, CO

Date of Photo: August, 1986

Photo 3 of 12

View looking northwest

Exterior-East & South Facades



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,

Colorado Springs, CO

Date of Photo: August, 1986

Photo 4 of 12

View looking southwest

Exterior- Rear Entrance Porch



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,
Colorado Springs, CO

Date of Photo: August, 1986

Photo 5 of 1.2

View looking south

Exterior-Northeast Elevation



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,
Colorado Springs, CO

Date of Photo: August, 1986

Photo 6 of 12

View looking north

Exterior-South Elevation



Gwynne/Love Residence
El Paso County, Colorado
Photographer: D.Abele
Locale of Negative: 1502 No. Custer,
Colorado Springs, CO
Date of Photo: August, 1986

Photo 7 of 12

View looking east southeast
Exterior-West Elevation



730

Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,

Colorado Springs, CO

Date of Photo: August, 1986

Photo 8 of 12

View looking West

Exterior Detail—Main Entrance Door



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,
Colorado Springs, CO

Date of Photo: August, 1986

Photo 9 of 12

View looking Southwest

Interior Detail - Stairwell wain-
scott



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,
Colorado Springs, CO

Date of Photo: August, 1986

Photo 10 of 12

View looking southeast

Interior-Central Entry Hall



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer,
Colorado Springs, CO

Date of Photo: August, 1986

Photo 11 of 12

View looking south

Interior Detail-Staircase



Gwynne/Love Residence

El Paso County, Colorado

Photographer: D.Abele

Locale of Negative: 1502 No. Custer

Colorado Springs, CO

Date of Photo: August, 1986

Photo 12 of 12

View looking Northeast

Interior - Van Briggles Fireplace