



Rumsey Hall
Cornwall CT

Photograph 1

Litchfield
County

General view northeast.
Congregational Church
on right.



RUMSEY HALL
CORNWALL, CT

Photograph 2

Litchfield
County

View northwest



RUMSEY HALL

CORNWALL, CT

Photograph 3

Litchfield

County

View Southwest



RUMSEY HALL

CORNWALL, CT

Photograph 4

Litchfield

County

View southeast



RUMSEY HALL
CORNWALL CT

Photograph 5

Litchfield

County

Window in front
pediment, view
north



RUMSEY HALL

CORNWALL, CT

Photograph 6

Litchfield

County

First floor, front

Stair, view

northeast



RUNSEY HALL
CORNWALL, CT

Photograph 7

Witchfield
County

First floor, left
front room, view
south



RUMSEY HALL

CORNWALL, CT

Photograph 8

Litchfield

County

First floor, window
in west wall of
left front room,
view northwest



RUMSEY HALL
CORNWALL CT

Photograph 9

Litchfield

County

First floor, mantel
in right front
section, view
southeast.



RUMSEY HALL

CORNWALL, CT

Photograph 10

Litchfield

County

First floor,
dining hall,

View southeast



RUMSEY HALL

CORNWALL, CT

Photograph 11

Litchfield
County

Second floor, hall
in east wing,
view east



RUMSEY HALL
CORNWALL, CT

Photograph 12

Litchfield
County

Second floor, front
apartment, view
northeast



RUMSEY HALL

CORNWALL, CT

Photograph 13

Litchfield

County

Second floor, front,
exposed structural
members, view east



RUMSEY HALL

CORNWALL, CT

Photograph 14

Litchfield County

Attic, roof parlin

Support system,

view north



RUMSEY HALL

On RHWALL, CT

Photograph 15

Litchfield County

Roof, front, west
side, original
fabric at left
plywood at right,
view west



Rumsey HALL
CORNWALL, CT

Photograph 16

Litchfield County

Barn/Gymnasium,
view northeast



RUMSEY HALL
CORNWALL, CT

Photograph 17

Litchfield
County

Historic view