

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED AP

APR 2 9 1975

AUG 6 1975

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Hatheway House

AND/OR COMMON

2 LOCATION

CITY. TOWN Suffield

\_\_VICINITY OF

COUNTY Hartford

STATE CT

**3 PHOTO REFERENCE** 

PHOTO CREDIT Clark Strickland

DATE OF PHOTO

4/10/75

NEGATIVE FILED AT Connecticut Historical Commission 59 So. Prospect St., Hartford, CT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. #1

Main (east) elevation; view southwest showing coach house (northwest of house) and carriage house (southwest of house).

INT: 2983-75



HATHEWAY

Form No. 10-301a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED APR 2 9 1975

DATE ENTERED

AUG 6

13/5

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Hatheway House

AND/OR COMMON

2 LOCATION

CITY, TOWN Suffield

\_\_\_VICINITY OF

COUNTY Hartford

STATE CT

3 PHOTO REFERENCE

PHOTO CREDIT Clark Strickland

DATE OF PHOTO 4/10/75

NEGATIVE FILED AT Connecticut Historical Commission CT 58 South Prospect St., Hartford, CT

4 IDENTIFICATION

bescribe view, direction, etc. if district, give building NAME & STREET Rear elevation, south end: view northeast

PHOTO NO. #2

INT: 2983-75

184



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

APR 2 9 1975

RECEIVED

DATE ENTERED AUG 6 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Hatheway House

AND/OR COMMON

2 LOCATION

CITY, TOWN

Suffield

\_\_\_VICINITY OF

COUNTY Hartford

TATE CT

**3 PHOTO REFERENCE** 

PHOTO CREDIT Clark Strickland

DATE OF PHOTO 4/10/75

NEGATIVE FILED AT Connecticut Historical Commission
59 South Prospect St., Hartford, CT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.  $_{\it \pm}$ 

North portice; view south

INT: 2983-75



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY
HECEIVED APR 2 9 1975

DATE ENTERED AUG 6 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Hatheway House

AND/OR COMMON

2 LOCATION

CITY. TOWN Suffield

\_\_VICINITY OF

COUNTY Hartford

STATE CT

**3 PHOTO REFERENCE** 

PHOTO CREDIT Clark Strickland

DATE OF PHOTO 4/10/75

NEGATIVE FILED AT Connecticut Historical Commission 59 South Prospect St., Hartford, CT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. #4

Coach house; view northwest



### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS U	SE ON	ILY			
	ΛC	R 2 9	107	r	
RECEIVED	Mr	7 6 7	, 13/	3	
DATE ENTE			NUG (	197	15

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1	NAME
1	INAME

HISTORIC Hatheway House

AND/OR COMMON

### 2 LOCATION

CITY. TOWN Suffield

\_\_\_VICINITY OF

COUNTY Hartford

STATE CT

#### **3 PHOTO REFERENCE**

PHOTO CREDITClark Strickland

DATE OF PHOTO 4/10/75

NEGATIVE FILED AT Connecticut Historical Commission 59 South Prospect St., Hartford, CT

### 4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

**РНОТО NO. #5** 

Carriage house; view northwest

INT: 2983-75

5/8



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

APR 2 9 1975

RECEIVED

AUG 6 1975

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

Hatheway House

AND/OR COMMON

2 LOCATION

CITY, TOWN Suffield

\_\_\_VICINITY OF

COUNTY Hartford

STATE CT

**3 PHOTO REFERENCE** 

PHOTO CREDIT Herman Marshall

DATE OF PHOTO 1970

NEGATIVE FILED AT Antiquarian and Landmarks Society, 394 Main St. Hartford, CT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

**РНОТО NO.** #6

Showing the front sitting room, downstairs, with French wallpapers.



### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED APR 2 9 1975

DATE ENTERED AUG 6 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

Hatheway House

AND/OR COMMON

2 LOCATION

CITY. TOWN Suffield

\_\_\_VICINITY OF

COUNTY Hartford

STATE C'I

**3 PHOTO REFERENCE** 

PHOTO CREDIT Herman Marshall

DATE OF PHOTO 1970

NEGATIVE FILED AT Antiquarian and Landmarks Society, 394 Main St., Hartford, CT

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. #7

Downstairs hallway, showing French wallpapers.



## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

APR 2 9 1975

RECEIVED

DATE ENTERED AUG 8 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1	NAME
---	------

HISTORIC Hatheway House

AND/OR COMMON

### 2 LOCATION

CITY. TOWN Suffield

\_\_\_VICINITY OF

COUNTY Hartford

STATE

CT

#### **3 PHOTO REFERENCE**

PHOTO CREDIT Herman Marshall

DATE OF PHOTO 1970

NEGATIVE FILED AT Antiquarian and Landmarks Society, 394 Main St., Hartford, CT

### 4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View showing Burbank kitchen in its restored state.

PHOTO NO.

#8