



BOULDER VALLEY
COMMUNITY HALL

AVAILABLE FOR
DAY OR HALF-DAY SESSION
CALL 866-8676

Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative:

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: May, 1987

Photo #1 of 9

View is west side of building. Shed at left
is part of Interstate Gas. Co. substation



Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative:

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of Photo: February, 1987

Photo #2 of 9

View from southeast showing second addition
added to east side in 1947



Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative;

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: June 1987

View #3 of 9

View of east side showing flat roof and ship-
lap siding on second addition.



Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: June, 1987

Photo #4 of 9

View of north side of building showing original windows on first addition and the shorter replacement windows on main hall to right of picture. Also shown, the lean-to coal shed.



Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative:

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: June 1987

Photo #5 of 9

Another view of coal shed on north side, the
surrounding cultivated farm land to the
east and trees on east edge of property



Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative:

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: June, 1987

Photo #6 of 9

Detail of tall casement window, the two types
of siding used and the soft brick chimney of
original building.





Boulder Vellely Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative:

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: October, 1986

Photo #7 of 9

Interior of main hall showing stage, double doors into dining room, oak floors, the built-in plank benches and the trophy case on far corner wall. Note the molding midway up walls for hanging pictures.



EXIT

Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative:

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: October, 1986

Photo #8 of 9

East end of dining room. Pole in center of room supports ceiling at the point where east wall was removed and the second addition was built on in 1947. To right is the kitchen and the folding doors to the far right open onto the stage in the meeting room.



GLASSES

88

DISHES

COOKING
VESSELS

Boulder Valley Grange Hall #131, Boulder
County, Colorado

Photographer: Anne Dyni

Locale of negative:

Mrs. John Dyni
2297 Park Lake Dr.
Boulder, CO 80301

Date of photo: June, 1987

Photo #9 of 9

View of kitchen taken from doorway into
dining room.