



Jonathan Newton Harris Residence

New London, Ct. 2/81

D.S. Plummer, Photograph 1

facade

Negative 35 on file at Ct. Hist. Comm.

Hartford, Ct.



Jonathan Newton Harris Residence

New London, Ct. 2/81

D.S. Plummer, Photograph 2

Detail, first floor window and surround

Negative 21 on file at Ct. Hist. Comm.

Hartford, Ct.



NO
TRESPASSING
VIOLATORS WILL
BE PROSECUTED

Jonathan Newton Harris Residence

New London, Ct. 2/81

D.S. Plummer, Photograph 3

Main entrance

Negative 22 on file at Ct. Hist. Comm.

Hartford, Ct.



Jonathan Newton Harris Residence

New London, Ct. 2/81

D.S. Plummer, Photograph 4

Detail, brownstone capital, main entrance

Negative 20 on file at Ct. Hist. Comm.

Hartford, Ct.



Jonathan Newton Harris Residence

New London, Ct. 2/81

D.S. Plummer, Photograph 5

Southeast elevation

Negative 25 on file at Ct. Hist. Comm.

Hartford, Ct.



Jonathan Newton Harris Residence

New London, Ct. 2/81

D.S. Plummer, Photograph 6

Northwest elevation

Negative 25 on file at Ct. Hist. Comm.

Hartford, Ct.



Jonathan Newton Harris Residence


New London, Ct. 2/81

D.S. Plummer, Photograph 7

Detail, stairway

Negative 8 on file at Ct. Hist. Comm.

Hartford, Ct.



Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S. Plummer, Photograph 8
Detail, plaster reveal
Negative 9 on file at Ct. Hist. Comm.
Hartford, Ct.



Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S. Plummer, Photograph 9
Drawing room mirror
Negative 5 on file at Ct. Hist. Comm.
Hartford, Ct.



Jonathan Newton Harris Residence

New London, Ct. 2/81

D.S. Plummer, Photograph 10

Interior door and surround, drawing room.

Negative 3 on file at Ct. Hist. Comm.
Hartford, Ct.



Jonathan Newton Harris Residence

New London, Ct. 2/31

D.S. Plummer, Photograph 11

Detail, plaster cornice in drawing room.

Negative 2 on file at Ct. Hist. Comm.

Hartford, Ct.