Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 1
facade
Negative 35 on file at Ct. Hist. Comm.
Hartford, Ct.

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 2
Detail, first floor window and surround
Negative 21 on file at Ct. Hist. Comm.
Hartford, Ct.

NO
TRESPASSING
VIOLATORS WILL
BE PROSECUTED

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 3
Main entrance
Negative 22 on file at Ct. Hist. Comm.
Hartford, Ct.

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S. Plummer, Photograph 4
Detail, brownstone capital, main entrance
Negative 20 on file at Ct. Hist. Comm.
Hartford, Ct.

FIRE
LANE

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 5
Southeast elevation
Negative 25 on file at Ct. Hist. Comm.
Hartford, Ct.

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S. Plummer, Photograph 6
Northwest elevation
Negative 25 on file at Ct. Hist. Comm.
Hartford, Ct.

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 7
Detail, stairway
Negative 8 on file at Ct. Hist. Comm.
Hartford, Ct.



Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 8
Detail, plaster reveal
Negative 9 on file at Ct. Hist. Comm.
Hartford, Ct.

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 9
Drawing room mirror
Negative 5 on file at Ct. Hist. Comm.
Hartford, Ct.

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 10
Interior door and surround, drawing room.

Negative 3 on file at Ct. Hist. Comm.
Hartford, Ct.

Jonathan Newton Harris Residence
New London, Ct. 2/81
D.S.Plummer, Photograph 11
Detail, plaster cornice in drawing room.
Negative 2 on file at Ct. Hist. Comm.
Hartford, Ct.