

Photo 1

General view looking northeast of facade at present




Photo 2

Original rendering as shown in the Fort Wayne Journal-Gazette, May 21, 1911, p. 5.



Photo 3

Drawing of the facade and east wall from Fort Wayne's Resources, 1913, p. 85.




Photo 4

General view looking southeast of the rear portion of the west wall



Photo 5

General view looking southwest of the north and east rear elevations



Photo 6

General view looking southwest in the first floor front area



Photo 7

Deatil looking west of first floor ceiling above modern drop panels



Photo 8

Detail looking northeast of the base of the front stairs on the first floor



Photo 9

Detail looking northeast of basement stair landing



Photo 10

Detail looking northwest of rear stair landing, first floor



Photo 11

General view looking southwest in the basement



Photo 12

General view looking northeast on the second floor



Photo 13

General view looking southeast of second floor windows



Photo 14

General view looking north on the third floor




Photo 15

General view looking south on the fourth floor



Photo 16

Detail view looking northwest of fourth floor stair and elevator landings




Photo 17

Detail view looking northwest on the fourth floor, showing typical side and rear window treatment