



Nancy Taylor No. 1 Oil Well Site
Vicinity of Haskell,
Muskogee Co., OK

Dianna Everett photo

27 May 1989

S.H.P.O.

Tank and Walkway, camera facing NNW

Well head is $\frac{1}{2}$ way between tank and walkway and 90' N.

Slush pit is to left of tank



Nancy Taylor No. 1 Oil Well Site

Vicinity of Haskell

Muskogee Co., Ok

Dianna Everett photo

27 May 1989

S.H.P.O.

Well casinghead, photographer facing West



Nancy Taylor No. 1 Oil Well Site
Vicinity of Haskell
Muskogee, OK

Dianna Everett, photo.

27 May 1989

S.H.P.O.

Pipe walkway, camera facing East



Nancy Taylor No. 1 Oil Well Site

Vicinity of Haskell

Muskogee, OK

Dianna Everett photo

27 May 1989

S.H.P.O.

Wooden storage tank, camera facing NE