



1. Shelter H, 1937

of Lewisville Park

27 Clark County, Washington

Photographer:

Janice Rutherford

1985, neg at Heritage Trust



2. Central Shelter, 1937-38
of Lewisville Park, *looking NE*
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



3. Central Shelter, 1937-38
of Lewisville Park, *looking S.E.*
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



4. Bathhouse, 1937-38
of Lewisville Park, *looking west*
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg:Heritage Trust



5. Caretaker's Cottage,

of 1936-37

27 Lewisville Park (*looking N.E.*)
Clark County, Washington
Photographer: Janice
Rutherford, 1985



6. Fireplace, Caretaker's
of Cottage
27 Lewisville Park
Clark County, Washington
Photographer: Janice
Rutherford, 1985



7. Shelter B, 1952 - 53

Lewisville Park

Clark County, Washington

Photographer:

Janice Rutherford

1985 Heritage Trust



SECTION
K

8. Shelter K, 1960s
of Lewisville Park
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



C 45532

of
27

9. Maintenance Shops 1 & 2
Lewisville Park, *looking N*
Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg:Heritage Trust



LADIES

10. Concrete Block Restroom
of
27 near Shelter B
Lewisville Park
Clark County, Washington
Photographer: Janice
Rutherford. 1985



11. Maintenance Building 6
of Lewisville Park
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



12. North Entry Gate
of Lewisville Park
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



CLARK COUNTY
LEWIS RIVER
COUNTY
PARK

13. Sign, Parkside (ne)
of Lewisville Park
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



CLARK COUNTY
LEWISVILLE
PARK

14. Sign, Roadside (sw)
of Lewisville Park
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



15. Slab Rock Water Pipe
Lewisville Park
Clark County, Washington
Photographer:
Janice Rutherford
1985 Heritage Trust

of
27



16. Water Heater
of
27 Lewisville Park
Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg:Heritage Trust



17.
of
27

Fire Ring
Lewisville Park
Clark County, Washington
Photographer:
Janice Rutherford



18. Roadside Feature near
Shelter D
Lewisville Park
Clark County, Washington
Photographer: Janice
Rutherford, 1985

of
27



19. Slab Rock Bollards
near Central Shelter
of
Lewisville Park
28
Clark County, Washington
Photographer: Janice
Rutherford, 1985



20. Original Sink, Shelter D
Lewisville Park
of Clark County, Washington
27 Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



21. Lava Water Pipe Near
of Shelter H
27 Lewisville Park
Clark County, Washington
Photographer: Jance
Putherford, 1985



22. Retaining Trail Wall On
of Northern Slope
27 Lewisville Park
Clark County, Washington
Photographer: Janice
Rutherford, 1985



23.
of
27

Typical Early Support
Plinth
Lewisville Park
Clark County, Washington
Photographer: Janice
Rutherford, 1985



24. Freelined Central Road
of Lewisville Park, *looking N*
27 Clark County, Washington
Photographer:
Janice Rutherford
1985 Neg: Heritage Trust



25. Ballfield at North End
Lewisville Park
of
Clark County, Washington
27
Photographer:
Janice Rutherford
1985 Neg. Heritage Trust



26. New Viewpoint On River
of Bank (neg:Heritage Trust)
27 Lewisville Park
Clark County, Washington
Photographer: Janice
Rutherford. 1985



27.
of
27

Swimming Area
Lewisville Park
Clark County, Washington
Photo: Janice Rutherford
1985 Neg:Heritage Trust Clark
Co.