



ANDERSONVILLE

ANDERSONVILLE
THIS MONUMENT WAS ERECTED BY THE
UNITED STATES ARMY AND NAVY
COMMISSIONERS OF THE BUREAU OF
THE NATIONAL ARCHIVES
AND THE NATIONAL ARCHIVES
AND THE NATIONAL ARCHIVES
AND THE NATIONAL ARCHIVES

Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

CIVIL WAR MONUMENT,

VIEW NORTHEAST

Photograph 1



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

4 EAST GRANBY ROAD,

VIEW NORTH

Photograph 2



Granby Center Historic District
Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut Historical
Commission

2 PARK PLACE ON LEFT, BUILDINGS
IN CENTER AND ON RIGHT ARE LESS
THAN 50 YEARS OLD AND ARE NOT IN
THE DISTRICT. VIEW NORTHEAST.

Photograph 3



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

213 SALMON BROOK STREET

SOUTH, VIEW NORTHWEST

Photograph 4



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

225, 227 AND 229 SALMON

BROOK STREET SOUTH, VIEW
NORTHWEST

Photograph 5



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

231, 233 AND 235 SALMON
BROOK STREET SOUTH,
VIEW NORTHWEST

Photograph 6



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission
229, 231, 233 AND 235

SALMON BROOK STREET

SOUTH, VIEW SOUTHWEST

Photograph 7



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

239 SALMON BROOK STREET
SOUTH, VIEW NORTHWEST

Photograph 8



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

245 SALMON BROOK STREET
SOUTH, VIEW WEST

Photograph 9



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

251 SALMON BROOK STREET
SOUTH, VIEW NORTHWEST
Photograph 10



Stony Hill Village

Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

251 AND 255 SALMON BROOK
STREET SOUTH, VIEW
SOUTHWEST

Photograph 11



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

261 AND 265 SALMON BROOK
STREET SOUTH, VIEW

SOUTHWEST

Photograph 12



220

Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

220 SALMON BROOK STREET

SOUTH, VIEW NORTHEAST

Photograph 13



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

226 SALMON BROOK STREET

SOUTH, VIEW SOUTHEAST

Photograph 14



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

248 AND 242 SALMON BROOK
STREET SOUTH, VIEW
NORTHEAST

Photograph 15



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

SOUTH CONGREGATIONAL CHURCH

INTERIOR, VIEW NORTHEAST

Photograph 16



Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

242, 248, 250 AND 246 REAR
SALMON BROOK STREET SOUTH,
VIEW NORTHWEST

Photograph 17



↗ NORTH GRANBY
↗ EAST GRANBY
↗ BRADLEY

Granby Center Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

252 AND 250 SALMON BROOK
STREET SOUTH, VIEW
NORTHEAST

Photograph 18



Granby Cetner Historic
District

Granby, CT

D. Ransom Photo, 1/85

Negative: Connecticut
Historical Commission

254 SALMON BROOK STREET
SOUTH, VIEW EAST

Photograph 19