

HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

East (facade) and south elevations, view northwest


1





HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

Detail of front entry, view west



HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

Detail of lean-to framing, showing extension of chimney girt



HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

Rear elevation, view northeast



HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

Kitchen fireplace, view east



HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

Niche in chimney stack, cellar level, view southwest



HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

Fireplace wall, south front room, view northeast



HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

North front upper room, view southwest



HRC Photo, 9/86 Negative filed with Conn. Hist. Comm., Hartford

Corner cupboard, north front room view northeast



HRC Photo, 9/86
Negative filed with Conn.
Hist. Comm., Hartford

Barn, north elevation, view west

10

APR 2 1 1987