

Hendricks Building (1897) (New York Store) 369 South Main Street Pendleton, Umatilla County, Oregon

Looking northwesterly over the central business district.

1. Bowman Hotel (a National Register property)

Matlock-Brownfield Building
 Masonic Temple
 Hendricks Building
 Empire Block

6. St. Elmo Hotel

1 of 7 - Aerial View

Sommerville House Research Photo, August 1981 104 SE 5th Street Pendleton, OR 97801



Hendricks Building (1897) (New York Store) 369 South Main Street Pendleton, Umatilla County, Oregon

2 of 7

Looking southwesterly along SW Emigrant Avenue showing continuity of the Emigrant Street (south) facades of the Hendricks Building (foreground) and Empire Block.

Sommerville House Research Photo, August 1981 104 SE 5th Street Pendleton, OR 97801



(New York Store) 369 South Main Street Pendleton, Umatilla County, Oregon

Hendricks Building (1897)

3 of 7

Looking southeasterly along South Main Street, showing Hendricks Building on North side of SW Emigrant Avenue and the Masonic Temple, Matlock-Brownfield Building and Bowman Hotel to the south.

Sommerville House Research Photo, August 1981 104 SE 5th Street Pendleton, OR 97801



Hendricks Building (1897)
(New York Store)
369 South Main Street
Pendleton, Umatilla County, Oregon
4 of 7

corner of building.

Detail of cast iron corner column, SE

Sommerville House Research Photo, August 1981 104 5th Street Pendleton, OR 97801



Hendricks Building (1897) (New York Store) 369 South Main Street Pendleton, Umatilla County, Oregon 5 of 7 Ground story interior prior to rehabilitation. Sommerville House Research Photo. August 1981 104 SF 5th Street Pendleton, OR 97801



Hendricks Building (1897)
(New York Store)
369 South Main Street
Pendleton, Umatilla County, Oregon
6 of 7

South and east (principal) facades

Historic view, ca. 1900.

Sommerville House Research Copy Photo August 1981 104 SE 5th Street Pendleton, OR 97801



Hendricks Building (1897) (New York Store) 369 South Main Street Pendleton, Umatilla County, Oregon

7 of 7

South and east (principal facades), showing remarkably little external change since the 1900 view. The face brick has been painted, and the beveled corner entry has been replaced

by display windows, but the cast iron columns are intact and each of seven corbeled brick flues stand above the parapet.

Sommerville House Research photo, August 1981 104 SE 5th Street Pendleton, OR 97801