



Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado
January 10, 1978

NOV 17 1978

Negative at CA Office of Historic Preservation
Northeast elevation
Photo #1

JUL 31 1978



Parkhurst Building

Santa Monica, California

Photographer: A. L. Hurtado

JUL 31 1978

January 10, 1978

Negative at CA Office of Historic
Preservation

East elevation

Photo #2

NOV 17 1978



Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado
January 10, 1978

NOV 17 1978

Negative at CA Office of Historic
Preservation
East elevation showing tower
Photo #3

JUL 31 1978



Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado
January 10, 1978

JUL 31 1978

Negatives at CA Office of Historic
Preservation

North elevation showing tower

NOV 17 1978

Photo #4



Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado
January 10, 1978

JUL 31 1978

NOV 17 1978

Negative at CA Office of Historic
Preservation
North elevation showing tower details
Photo #5



Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado

JUL 31 1978

January 10, 1978

Negative at CA Office of Historic Preservation

NOV 17 1978

Tower from roof showing finials and cupola
Photo #6



Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado

NOV 17 1978

January 10, 1978

Negative at CA Office of Historic P.
Preservation

Cupola

Photo #7

JUL 31 1978



Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado
January 10, 1978

JUL 31 1978

Negative at CA Office of Historic
Preservation
Detail, brickwork on tower
Photo #8

NOV 17 1978



PARKHURST
BUILDING

1 9 2

181-185

Parkhurst Building
Santa Monica, California
Photographer: A. L. Hurtado
January 10, 1978
Negative at CA Office of Historic
Preservation
East elevation, scalloped parapet
Photo #9

JUL 31 1978

NOV 17 1978



PARKHURST
BUILDING

1 9 2 7



181·185

Parkhurst Building

Santa Monica, California

Photographer: A. L. Hurtado

January 10, 1978

Negative at CA Office of Historic
Preservation

East elevation, detail, side entrance

Photo #10

JUL 31 1978

NOV 17 1978



Parkhurst Building

Santa Monica, California

Photographer: A. L. Hurtado

January 10, 1978

Negative at CA Office of Historic

Preservation

Interior

Photo #11

JUL 31 1978

NOV 17 1978



Parkhurst Building

Santa Monica, California

Photographer: A. L. Hurtado

January 10, 1978

Negative at CA Office of Historic
Preservation

Interior, skylight

Photo #12

JUL 31 1978

NOV 17 1978