



#1 Sanford-Curtis-Thurber House
Newtown, CT Fairfield Co
View northwest showing front and east elevation
Kate Ohro photograph 5/06



#2 Sanford-Curtis-Thurber House
Newtown, CT Fairfield Co
view south west showing rear and east elevations
Kate Ohno photograph 5/06

1800




#3 Sanford-Curtis-Thurber House
Newtown, CT Fairfield Co.
front entrance.
Kate Ohno photograph 5/06



4 Sanford-Curtis-Thurber House
Newtown, CT Fairfield Co.
view east showing west elevation, porch and corner
Kate Ohno photograph 5/06



#5 Sanford-Curtis - Thurker House
Newtown, CT Fourtield Co
side entrance, west elevation
Kate Okn - photograph 5/06



#6 Sanford-Curtis - Timber House
Newtown, CT Fairfield Co
Side door from southwest front room
Kate Ohro photograph 5/06



7 Sanford-Curtis-Thurber House
Wentown, CT Fairfield Co
main staircase
Kate Ohno photograph 5/06



#8 Sanford Curtis - Thurber House
Newtown, Ct Fairfield Co.
last parlor showing fireplace
Kate Ohno photograph 5/06



9 Sanford-Curtis-Thurber House
Newtown CT Fairfield Co
southeast front chamber, second floor
Kate Ohno photograph 5/06



#10 Sanford-Curtis - Thurber House
Newtown, CT Fairfield Co
James Thurber's attic work room
Kate Ohno photograph 5/06



11 Sanford-Curtis - Thuerber House
Newtown, CT Fairfield Co
barn view west
Kate Ohne photograph 5/06



12 Sanford - Cur Ms - Thurber House
Newtown, CT Fairfield Co.
view southeast showing cottage and barn in foreground and
main house in background
Kate Ohno photograph 5/06