

Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs,

B/ASHP, Hall of Records, Dover, Delaware

Description: 3/4 View from northeast

Photograph Number: 1



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware

Description: Facade from east.

Photograph Number: 2



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June 1978

Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware
Description: Rear showing 2 small outbuildings included in
the nominated area from northwest.

Photograph Numbers 3

JUL & 6 1978



John B. Nelson House (N-3939) Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978 Location of Negative: Div. of Historical & Cultural Affairs. B/A&HP, Hall of Records, Dover, Delaware 19901 Description: South endwall showing added stairway window

Photograph Number: 4 JUL 2 6 1978

Name:



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901
Description: Southeast room of first floor - stairhall

Photograph Numbers 5



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: 1978 - June

Location of Negative: Div. of Historical & Cultural Affairs,

B/ASHP, Hall of Records, Dover, Delaware 19901 Description: Northeast room on first floor, North wall

with fireplace and butterfly curboard

Photograph Number:



Name: John B. Nelson House

Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June 1978

Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901
Description: Detail of butterfly cupboard in Northeast

first floor room

Photograph Number:

JUL 26 1978

DEC 8 197



Name: John B. Nelson House (N-3939) Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of door to wing on fireplace wall in northeast first floor room

Photograph Numbers



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of Greek Revival window architrave in first floor northeast room

Photograph Number: 9



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative:Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of winding stair casing in northwest first floor room.

Photograph Number: 10



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs,

B/ASHP, Hall of Records, Dover, Delaware 19901

Description: Detail of dog-eared door architrave in southwest first floor room

Photograph Number: 11

JUL 2 6 1978

1978



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of main stair leading to second floor from southeast stairhall.

Photograph Number: 12

JUL 261978



Location: Near Port Penn, Delaware

Photographer: Dean Nelson

Date: June, 1978

Location of Negative: Div. of Historical & Cultural Affairs, B/A & HP, Hall of Records, Dover, Delaware 19901

Description: Parelled endwall in second floor northeast room.

Photograph Number: 13

JUL 261978



Location: near Port Penn, New Castle Co., DE.

Photographer: Staff, B/AHP

November, 1978

Location of Negativen Div. of Hist. & Cult. Aff.,

Hall of Records, Dover, DE

Description: Views of outbuildings as described below (buildings numbered as on sketch map)

## Photograph Number:

- 1. Looking northeast from house towards the large animal barn with attached wings (#6,7,8).
- Looking southwest from field. Feed storage barn in forground (#4) chicken house & gable roofed shed in background (#3,2).
- Looking northwest towards feed barn and 3. attached pole shed (#4,5).
- Looking south between barns towards the house .
  - 5. View of barn & pole shed (#4,5).
  - 6. Looking north towards barns from drive.