



81A-296

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: October, 1981
Negative filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn; view
facing West
Photograph 1



81-A-296

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: October, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn; view
facing West-Northwest
Photograph 2



81-A-296

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: October, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn; view
facing Northwest
Photograph 3



E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: October, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn, detail,
front entrance
Photograph 4

81-#296



E. S. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: October, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. S. Stratton's Inn, rear
entrance, west elevation
Photograph 5

81-H-305



East Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: October, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: East Stratton's Inn, detail,
rear entrance
Photograph 6

81-7-296



81-A-305

East Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: November, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: East Stratton's Inn, mantelpiece,
tap room
Photograph 7



81A-305

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: November, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn, portion of
mantelpiece, and closet, tap room
Photograph 8



81A-305

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: November, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn, mantelpiece,
parlor
Photograph 9



81-A-305

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: November, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn, fireplace,
kitchen
Photograph 10



81-A-305

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: November, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn, detail of
kitchen fireplace showing beehive oven on
left
Photograph 11



81-A-305

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: November, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn, interior side
of rear door in kitchen
Photograph 12



81-A-305

E. Stratton's Inn
Brookfield, Vermont
Credit: Margaret N. DeLaittre
Date: November, 1981
Negative Filed at Vermont Division for
Historic Preservation
Description: E. Stratton's Inn, mantelpiece,
second floor ballroom
Photograph 13