

grapher facing north.

Photographer: James R. Lockhart
Negatives Filed: Georgia Department of
Natural Resources
Date: March, 1981
Description (1 of 7): Street side; photo-



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: March, 1981 Description (2 of 7): Railroad side; photographer facing east.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: March, 1981 Description (3 of 7): Rear of depot, and freight platform; photographer facing southwest.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of
Natural Resources
Date: March, 1981
Description (4 of 7) Detail railroad side;
photographer facing southeast.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: March, 1981 Office; photographer Description (5 of 7): facing southwest.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: March, 1981 Description (6 of 7): Freight area; photographer facing northeast.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: March, 1981 Description (7 of 7): Waiting Room; photographer facing west.